


ko	사용 설명서 원본 - 플런지 쏘	10
en	Original Instructions - Plunge-cut saw	23


TSV 60 KEBQ





Festool GmbH Wertstraße 20 73240 Wendlingen Germany +49 (0)70 24/804-0 www.festool.com






































https://Festool.com/QuickGuide-TSV60K



목차

1	기호	.10
2	안전 수칙	
3	기본 용도	14
4	기술 제원	
5	공구 구성 요소	.15
6	최초 작동	15
7	주 장치 조절	. 16
8	스코어링 조절	.17
9	전동 공구를 이용한 작업	19
10	킥백스톱	
11	유지보수 및 관리	21
12	액세서리	22
	환경	
14	일반 지침	22
	문의	

기호 1



일반적인 위험에 대한 경고



감전에 대한 경고



사용 설명서, 안전 수칙을 읽으십시오.



귀마개를 착용하십시오.



공구를 교체할 때는 반드시 보호 장갑을 착 용하십시오.



방진 마스크를 착용하십시오.



보안경을 착용합니다.



전원 플러그 분리



←급→ 전원 케이블 분리



전원 케이블 연결



톱과 톱날의 회전 방향



킥백스톱 기능



((☜ 전기 역학적인 퀵 브레이크 기능



가정용 쓰레기로 폐기하지 마십시오.



공구 장비에는 데이터 저장을 위한 칩이 포 함되어 있습니다. 단원 참조 14.1




유용한 정보, 지침



보호 등급 ||

안전 수칙

전동 공구 관련 일반 안전 수칙 2.1



모든 안전 수칙 및 지침은 언제든지 참조할 수 있도 록 잘 보관하십시오.

본 안전 수칙에서 사용되는 '전동 공구'는 (전선을 통 해) 전기 동력을 얻는 공구와 (전선 없이) 배터리에 서 전기 동력을 얻는 공구를 말합니다.

1 작업장 안전

- a. 작업장을 잘 정돈하고, 밝은 조명을 사용하십시 **오.** 정리정돈 상태가 불량하거나 조명이 어두운 작업장에서는 사고가 발생할 수 있습니다.
- b. 가연성 액체, 기체 또는 분진이 있어 폭발 위험 이 있는 작업장에서는 전동 공구를 사용하지 마 십시오.전동 공구에서 발생하는 불꽃으로 인해 분진 또는 가연성 기체가 발화할 수 있습니다.
- 전동공구를 사용할 때, 어린이들이나 다른 사람 들이 작업장에 접근하지 못하게 하십시오.주위 가 산만하면 전동 공구를 제대로 통제하지 못할 수 있습니다.

2 전기 안전

- 전동 공구의 커넥터 플러그를 소켓에 올바르게 끼워야 합니다. 플러그를 어떤 식으로든 변형 해서는 안 됩니다. 접지된 전동 공구에서 어댑 터 플러그를 사용해서는 안 됩니다. 변형되지 않은 플러그와 호환되는 소켓을 사용하면 감전 위험이 줄어듭니다.
- b. 파이프, 히터, 전기/가스렌지, 냉장고 등의 접지 표면과 직접 접촉하면 안 됩니다.신체가 접지되 면, 감전 위험이 높아집니다.
- 전동 공구를 비나 습기에 노출시키지 마십시오. 전동 공구에 물이 들어가면 감전 위험이 높아집 니다.
- d. 연결 케이블로 전동 공구를 운반하거나 매달아 서는 안 되며, 연결선을 당기면서 소켓에서 플 러그를 빼면 안 됩니다. 연결 케이블이 고열, 오 일, 날카로운 모서리, 이동하는 물체에 노출되 지 않도록 주의하십시오. 연결 케이블이 손상되 거나 엉키면 감전 위험이 높아집니다.
- e. 실외에서 전동 공구를 사용하는 경우에는 실외 용 연장 케이블을 사용하십시오.실외용 연장 케 이블을 사용하면 감전 위험이 줄어듭니다.

f. **습한 장소에서 전동 공구를 사용해야 하는 경우** 에는 누전 차단기를 사용하십시오.누전 차단기를 사용하면 감전 위험이 줄어듭니다.

3 작업자 안전

- a. 전동 공구를 사용할 때는 주의하면서 작업에 집 중하십시오. 피곤한 상태이거나 약물, 주류 또 는 의약품을 복용한 상태에서는 전동 공구를 사 용하지 마십시오. 전동 공구를 사용할 때는 한 순간의 부주의가 심각한 상해를 초래할 수 있습 니다.
- b. 항상 개인 보호 장비와 보안경을 착용하십시오. 전동 공구의 유형과 작업 방식에 따라 부상 방 지를 위해 방진 마스크, 미끄럼 방지 안전화, 안 전모, 귀마개 등의 개인 보호 장비를 착용해야 부상 위험이 줄어듭니다.
- c. 공구가 갑자기 작동하지 않도록 주의하십시오. 전동 공구를 전원 공급 장치 또는 배터리에 연 결하거나, 집어 들거나 운반하려는 경우에는 먼 저 공구의 전원이 꺼져 있는지 확인하십시오. 전동 공구를 운반할 때 손가락이 스위치에 닿아 있거나 전동 공구가 켜진 상태에서 전원 공급 장치에 연결하면 사고가 발생할 수 있습니다.
- d. 전동 공구를 켜려면 먼저 조정 도구 또는 렌치를 분리하십시오.전동 공구의 회전부에 다른 도구나 렌치가 있으면 부상이 발생할 수 있습니다.
- e. 불안정한 자세로 작업하지 않도록 주의하십시 오. 항상 안정적으로 선 자세에서 평형을 유지 하십시오. 자세가 안정적이면 예상치 못한 상황 에서도 전동 공구를 효과적으로 통제할 수 있습 니다.
- f. 작업에 적합한 보호복을 착용하십시오. 너무 헐 렁한 복장이나 장신구를 착용해서는 안 됩니다. 작동부에 머리카락 또는 옷이 닿지 않도록 주의 하십시오. 헐렁한 옷, 장신구 또는 긴 머리카락 은 회전 부분에 말려 들어갈 수 있습니다.
- g. 집진기 및 분진 수거 장치를 설치할 수 있는 경 우, 올바르게 연결한 후 사용해야 합니다.집진 기를 사용하면 분진에 의한 사고 발생을 줄일 수 있습니다.
- h. 안전 수칙을 무시해서는 안 됩니다. 전동 공구를 여러 번 사용해서 잘 알고 있는 경우에도 반드시 안전 사용 규칙을 따르시기 바랍니다.한순간의 부주의가 심각한 상해를 초래할 수 있습니다.

4 전동 공구의 사용 및 작동 방법

a. 전동 공구를 과부하 상태로 사용하지 마십시오. 원래의 작업 용도로만 전동 공구를 사용하십시 오.호환이 가능한 전동 공구를 사용하면 작업 효율이 향상되며 지정된 전원 범위에서 더욱 안 전하게 작업할 수 있습니다.

- b. **스위치가 제대로 작동하지 않는 전동 공구는 사 용하지 마십시오.**정상적으로 켜거나 끌 수 없는 전동 공구는 위험하므로 수리해야 합니다.
- c. 기기의 설정을 변경하거나, 공구 비트를 교체하 거나, 전동 공구를 사용하지 않고 옆에 내려 놓 으려면 먼저 소켓에서 플러그를 뽑으십시오. 배 터리가 탈착식이면 배터리를 분리하십시오.이 와 같이 조치하면 전동 공구가 갑자기 작동하는 사고를 예방할 수 있습니다.
- d. 사용하지 않는 전동 공구는 어린이의 손이 닿지 않는 곳에 보관하십시오. 공구 사용에 익숙하지 않거나 본 설명서를 숙지하지 않은 사람이 전동 공구를 사용하는 일이 없도록 하십시오. 사용 경 험이 없는 작업자가 전동 공구를 사용하면 사고 가 발생할 수 있습니다.
- e. 전동 공구와 공구 비트를 주의해서 관리하십시 오. 작동부가 제대로 작동하고 걸리지 않는지 확인하십시오. 손상되거나 심하게 파손된 부분 이 전동 공구의 작동을 방해하고 있지 않은지도 확인해야 합니다. 파손된 부분이 있으면 전동 공구를 사용하기 전에 수리하십시오.관리가 미 흡한 전동 공구에서 많은 사고가 발생하고 있습 니다.
- f. **컷팅 공구의 날은 날카롭고 청결한 상태로 유지 하십시오.**컷팅날을 날카롭게 유지하고 잘 관리 하면 걸림 현상이 줄어들고 공구를 더욱 쉽게 조작할 수 있습니다.
- g. 본 수칙에 따라 전동 공구와 공구 비트 등을 사용하십시오. 작업 조건이 처리할 작업에 적합한지 확인하십시오.전동 공구를 정해진 용도가 아닌 다른 용도로 사용하면 위험한 상황이 발생할수 있습니다.
- h. **손잡이와 손잡이면은 건조한 상태로 청결하게** 유지하고, 오일 및 구리스가 남아 있지 않게 하십시오.손잡이와 그립면이 미끄러우면 미끄러우면 예상치 못한 상황에서 전동 공구를 안전하게 조작하지 못할 수 있습니다.

5 서비스

- a. **공인된 전문가에게 전동 공구의 수리를 의뢰하 고 정식 부품을 사용하십시오.** 이와 같이 관리해야 전동 공구를 안전하게 사용할 수 있습니다.
- b. 수리 및 유지보수 작업 시에는 정품만 사용하십시오. 호환이 되지 않는 액세서리 또는 부품을 사용하면 감전 등의 상해 사고가 발생할 수 있습니다.

2.2 전기원형톱 관련 안전 지침

절단 방법

- 위험! 절단 영역 안쪽과 톱날 부분에 손을 대지 마십시오. 다른 한손으로 보조 손잡이나 모터 하우징을 잡으십시오. 양손으로 공구를 잡고 있으면 톱날로 인한 부상을 방지할 수 있습니다.

- **가공물 아래쪽에 손을 대지 마십시오.** 아래쪽은 보호 커버로 톱날이 보호되지 않습니다.
- 가공물 두께에 맞춰서 절단 깊이를 변경하십시
 오. 가공물 아래로 톱니 하나보다 작은 높이가 보여야 합니다.
- 절단할 가공물을 절대로 손 안이나 다리 위로 고정하지 마십시오. 안정적인 마운트에 가공물 을 고정하십시오. 가공물을 올바르게 고정하는 것은 신체 접촉, 톱날 끼임 또는 제어력 상실의 위험을 최소화하기 위해 중요합니다.
- 작업할 때 눈에 보이지 않는 전기 케이블이나 연결선에 공구 비트가 닿을 가능성이 있을 경우 전동 공구는 절연된 손잡이 면으로만 잡으십시 오. 전압이 흐르는 전선과 접촉하면 전동 공구의 금속 부품에도 전압이 흘러서 감전이 발생할수 있습니다.
- **길이 절단 시 반드시 스톱 장치나 직선 엣지 가이드를 사용하십시오.** 절단 정확성을 높이고 톱날 끼임의 위험을 줄여줍니다.
- 항상 올바른 사이즈와 연결홀(예: 마름모형 또는 원형)에 맞는 톱날을 사용하십시오. 톱의 장착 부품에 맞지 않은 톱날은 불안정하게 작동하여 통제력을 잃게 만듭니다.
- **손상되었거나 적합하지 않은, 톱날 클램핑 플랜** 지나 클램핑 나사를 사용하지 마십시오. 톱날 클램핑 플랜지와 클램핑 나사는 공구에 따라 최적의 성능과 작업 안전을 위해 특수 설계되었습니다.

킥백 - 발생 원인 및 해당 안전 수칙

- 킥백은 톱날이 걸리거나 끼이거나 방향이 잘못 되었을 때 나타나는 갑작스러운 반응이며, 제어 되지 않은 톱이 들어올려지면서 가공물에서 벗 어나 작업자 쪽으로 향합니다
- 좁아진 톱 간극에 톱이 걸리거나 끼이면, 막힘 이 발생하면서 구동력에 의해 기기가 작업자 쪽 으로 반동됩니다.
- 절단선의 톱날이 뒤틀리거나 잘못 정렬되면, 톱 날의 뒤쪽 톱니가 가공물 표면에 걸리면서 톱날 이 톱 간극을 벗어나 작업자 쪽으로 향하게 됩니다.

톱을 잘못된 방법으로 또는 미숙하게 사용하는 경우에 킥백이 발생할 수 있으며, 다음 방법으로 이를 예 방할 수 있습니다.

- 양손으로 단단히 공구를 잡고, 반동력을 막을 수 있는 위치에 팔을 두십시오. 톱날은 반드시 작업자의 측면에 있어야 하고, 절대로 작업자의 신체와 일직선으로 두어서는 안 됩니다. 킥백 현상이 발생한 경우 톱이 뒤로 튈 수 있지만, 적 절한 조치를 취하면 작업자가 반동력을 막을 수 있습니다.
- 톱날 끼임이나 작업 중단이 발생했을 때는 ON/OFF 스위치를 해제하고, 톱날이 정지할 때까지 톱을 가공물 안에 그대로 두십시오. 톱

- 날이 움직이는 동안은 절대로 톱을 가공물에서 제거하려고 하거나 뒤로 빼내려고 해서는 안 되며, 그렇지 않을 경우 킥백이 발생할 수 있습니다. 톱날 끼임이 발생하는 원인을 조사하고 해결하십시오.
- 가공물에 끼인 톱을 다시 시작하고자 할 때는 톱 간극에 있는 톱날의 중심을 조절해서 톱니가 가공물에 끼이지 않도록 하십시오. 톱날이 끼인 상태에서 톱 작업을 다시 시작하면 톱날이 가공 물 밖으로 나오거나 킥백이 발생할 수 있습니 다.
- 톱날 걸림으로 인해 킥백이 발생하지 않도록 큰 패널에 지지대를 설치하십시오. 대형 패널은 자체 중량 때문에 아래로 처지는 경향이 있습니다. 판재의 경우 톱 간극 주변과 가장자리 양측을 모두 지지해 주어야 합니다.
- 무디거나 손상된 톱날을 사용하지 마십시오. 무 디거나 정렬이 잘못된 톱니는 좁은 톱 간극으로 인해 마모 증가, 톱날 끼임 및 킥백을 유발합니다.
- 절단 작업 전에 절단 깊이 및 각도 조절장치를 고정하십시오. 절단 작업 중에 조절 장치가 변 경되면 톱날 끼임이나 킥백이 발생할 수 있습니다.
- 기존의 벽 부분 또는 보이지 않는 다른 영역을 절단할 때는 각별히 주의하십시오. 절단 중에 플런지 컷 톱날이 숨어 있는 물체에 가로막혀서 킥백을 유발할 수 있습니다.

보호 커버의 기능

- 사용 전에 보호 커버가 올바르게 닫혀 있는지 점검하십시오. 보호 커버가 원활하게 움직이지 않고 즉시 닫히지 않으면 쏘잉 공구를 사용하지 마십시오. 절대로 보호 커버를 클램핑하거나 고 정하지 마십시오. 톱날 보호 기능이 작동되지 않을 수도 있습니다. 쏘잉 공구가 실수로 바닥 에 떨어질 경우 보호 커버가 휠 수 있습니다. 보 호 커버가 원활하게 움직이고 모든 절단 각도 및 절단 깊이에서 톱날이나 다른 부품을 건드리 지 않는지 확인하십시오.
- 보호 커버용 스프링의 상태 및 기능을 점검하십시오. 보호 커버와 스프링에 문제가 있을 경우기기 사용 전에 톱 장치를 정비하십시오. 손상된 부분이 있거나 접착제가 남아 있거나 칩이쌓여 있으면 보호 커버가 제대로 작동하지 않습니다.
- 직각이 아닌 각도로 "플런지 컷"을 진행할 때는 톱의 베이스 플레이트가 이동하지 않도록 주의하십시오. 측면으로 이동하면 톱날 끼임으로인해서 킥백 현상이 일어날 수 있습니다.
- 보호 커버가 톱날을 덮지 않은 상태에서 워크벤 치나 바닥 위에 톱을 내려놓지 마십시오. 아직 멈추지 상태로 노출된 톱날은 톱을 절단 방향 반대로 움직이면서 앞에 놓인 것들을 절단하게 됩니다. 톱이 멈추는 시간을 고려하십시오.

스캔 웨지 [1-21]의 기능(킥백스톱 기능)

- 톱날을 교체할 때마다 바람을 불거나 브러시를 사용해 스캔 유닛 [5-9]을 청소하십시오. 스캔 유닛이 오염되면 킥백스톱 기능에 영향을 주고, 이로 인해서 톱날 제동에 방해가 될 수 있습니 다.
- 스캔 웨지가 휜 상태에서는 톱을 작동하지 마십 시오. 약간의 손상에도 톱날 제동이 느려질 수 있습니다.

사전 조립된 톱날 관련 안전 지침 2.3

용도

- 톱날의 최대 회전 속도가 기준 속도를 초과하지 않도록 기준 속도 범위를 준수해야 합니다.
- 사전 조립된 톱날은 원형톱에만 사용됩니다.
- 스코어링 톱날의 경우 Festool TSV 60 사용 을 위해서만 고안된 것입니다. 목재 및 목재 유 사 소재에 대한 가공은 물론 코팅된 형태의 플 라스틱 가공 또는 고경도 자재 가공에 적합합니 다.
- 공구의 포장 제거, 포장 및 취급(예: 공구 장비 에 장착) 시 조심하십시오. 날카로운 칼날로 인 해 부상을 입을 수도 있습니다!
- 공구 취급 시 보호 장갑을 착용한 상태로 공구 를 운반하면 그립 안정감이 향상되고 부상 위험 을 줄일 수 있습니다.
- 몸체가 파손된 원형 톱날은 교체하십시오. 톱날 은 수리할 수 없습니다.
- 톱니 두께가 1 mm 미만인 고정식 원형 톱날 (연납 처리된 톱니)은 사용하지 마십시오.
- 경고! 육안상 균열이 발견되거나 또는 날의 상 태가 무디거나 파손된 경우에는 공구를 사용하 지 마십시오.

장착 및 고정

- 공구가 사용 중에 풀리지 않도록 고정하십시오.
- 공구 장착 시 공구 허브나 공구의 클램핑 표면 에서 클램핑이 이뤄지는지 그리고 절단 시 다른 부품과 접촉이 발생하지 않는지 확인해야 합니 다.
- 렌치를 연장하거나 해머 임팩트를 이용하여 조 이지 마십시오.
- 클램핑 표면에 있는 오염물, 기름기, 오일 및 물 기 등을 제거하십시오.
- 제조사의 사용설명서에 따라 클램핑 스크류를 조이십시오.
- 공구의 스핀들 직경에서 원형 톱날의 구멍 직경 을 조정할 때에는 단단히 고정되어 있는 링(예: 압입된 링 또는 부품으로 고정된 링)을 사용해 야 합니다. 느슨한 상태의 링을 사용하지 마십 시오.
- 톱날 교체 후에는 사용 설명서에 따라 공구 장 비를 점검하고 필요한 경우 다시 설정해야 합니 다.

유지보수 및 관리

- 수리 작업 또는 샌딩 작업은 Festool의 고객 서 비스 센터 또는 전문가에 의해서만 수행되어야 합니다.
- 공구의 구조를 변경하지 마십시오.
- 정기적으로 공구에 있는 레진을 제거하고, 공구 를 세척하십시오(pH 4.5 ~ 8 수준의 세척제).
- 무딘 날의 단면은 절단날의 최소 두께인 1 mm 까지 추가로 갈 수 있습니다.
- **스코어링 톱날**은 재연마할 수 없습니다.
- 공구는 적절한 포장재에 담아 운반하십시오 -그렇지 않을 경우 부상을 입을 수 있습니다!

2.4 기타 안전 지침

- 적합한 개인 보호 장비를 착용하십시오. 방호용 귀마개, 보안경, 분진 발생 작업 시 방진 마스크.
- 작업 시 유해한 독성이 포함된 분진이 발생할 수 있습니다(예: 납이 함유된 도료, 일부 목재류 및 금속). 이런 분진을 작업자나 근처에 있는 사 람들이 만지거나 흡입하면 위험할 수 있습니다. 해당 국가에 적용되는 안전 규정에 유의하십시 오.
- 사용자의 건강을 보호할 수 있도록 적합한 호흡 용 마스크를 착용하십시오. 밀폐된 공간에서는 충분히 환기를 시키고 이동식 집진기를 연결합 니다.
- 본 전동 공구를 작업대 안에 장착하면 안 됩니 다. 타사의 작업대나 직접 만든 작업대에 장착 할 경우 공구의 안전을 보장할 수 없으며, 심각 한 사고가 발생할 수 있습니다.
- 하우징 부품에 균열이나 백화 현상 등의 손상이 있는지 점검하십시오. 파손된 부분이 있으면 전 동 공구를 사용하기 전에 수리하십시오.
- 탐지기를 이용해 작업 장소에 숨겨진 전선이 있 는지 확인하거나 또는 현지 전기 공급업체에 문 의하십시오. 공구 비트가 전압이 흐르는 전선과 접촉하면 화재 및 전기 쇼크가 발생할 수 있습 니다. 가스관이 손상되면 폭발이 일어날 수 있 습니다. 수도관에 유입되면 물적 피해가 발생할 수 있습니다.
- 전동 공구를 케이블 부분으로 들어올리거나 운 반하지 마십시오.

2.5 알루미늄 가공

알루미늄 가공 시 안전을 위한 준수 사항:



- 보안경을 착용하십시오!
- 전동 공구 모터 하우징에 쌓인 분진을 정기적으 로 청소합니다.
- 알루미늄 절단에 적합한 톱날을 사용하십시오.
- 모니터링창을 닫으십시오.
- 고장 전류(FI, PRCD) 및 과전류 차단기를 연결 합니다.

판재를 절단할 때는 석유 오일로 윤활 작업을 해야 하며, 두께가 얇은 프로파일(3 mm 이하) 은 윤활제 없이 가공할 수 있습니다.

2.6 배출값

EN 60745에 따라 산출된 대표적인 값은 다음과 같 습니다.

음압 레벨 $L_{PA} = 93 \text{ dB(A)}$ 소음 레벨 $L_{WA} = 101 \text{ dB(A)}$ 오차 K = 3 dB





주의

전동 공구를 이용한 작업 시 소음 방출로 인해 청 각이 손상될 수 있습니다.

▶ 귀마개를 사용하십시오.

진동 배출 값 a, (3방향의 벡터합) 및 불확도 K 산출 기준EN 60745:

목재 절단 $a_h < 2.5 \text{ m/s}^2$ $K = 1.5 \text{ m/s}^2$ 금속 절단 $a_h < 2.5 \text{ m/s}^2$

 $K = 1.5 \text{ m/s}^2$

제시된 배출값은(진동, 소음)

- 전동 공구를 비교하는 용도로 사용됩니다.
- 작업 중의 진동 및 소음 부하와 관련된 예비값 을 산출하는 용도로도 사용됩니다.
- 전동 공구의 기본 용도를 나타냅니다.

주의

배출 값은 제시된 값과 차이가 있을 수 있습니다. 사용하는 공구 및 가공물의 종류에 따라 다릅니다.

- 전체 작동 사이클이 진행되는 동안 실제 가해진 부하를 평가하십시오.
- ▶ 실제 부하에 따라 작업자를 보호하기 위한 적절 한 안전 조치를 정해야 합니다.

기본 용도 3

플런지쏘는 목재, 목재와 유사한 소재, 석고 및 시멘 트 계열의 섬유판 및 플라스틱 절단에 적합합니다.

Festool의 알루미늄용 특수 톱날을 장착하면 알루 미늄을 절단하는 용도로도 사용할 수 있습니다. 석면이 함유된 소재를 작업해서는 안 됩니다. 절단석 및 연마석을 사용하지 마십시오.



↑ 출시 . 습니다. .. 잘못된 사용으로 인한 책임은 사용자에게 있

3.1 스코어링

스코어링은 가이드 레일과 결합한 상태에서 다음 가 공 시에만 활성화할 수 있습니다

- 목재 및 목재류
- 라미네이트 또는 솔리드 형태의 플라스틱

3.2 톱날

아래의 사양을 충족하는 톱날만 사용하십시오.

- EN 847-1에 따른 톱날
- 톱날 직경 168 mm
- 절단 폭 1.8 mm
- 고정 구멍 20 mm
- 기본 톱날 두께 1.2 mm
- 회전속도 9 500 min-1 이하에 적합함

거스러미 발생이 없는 깨끗한 절단을 위해 스코어링 과 결합하여 사용하기에 다음 톱날 제품이 적합합니 다.

- 원형 톱날 HW 168x1.8x20 WD42
- 원형 톱날 HW 168x1.8x20 TF52

스코어링 시 다음 데이터를 포함하는 Festool만 사 용합니다.

- EN 847-1에 따른 톱날
- 톱날 직경 47 mm
- 절단 폭 1.9 2.5 mm
- 고정 구멍 6.35 mm
- 기본 톱날 두께 1.6 mm
- 회전속도 26 000 min-1 이하에 적합함

EN 847-1에 부합하는 Festool 톱날.

각 톱날에 알맞은 소재만 절단합니다.

기술 제원 4

플런지쏘	TSV 60 KEBQ	TSV 60 KEB
전원 연결선 제거 가능함(plug it)	\checkmark	×
소비 전력	1 500W	
회전 속도	3 000 - 6 800 rpm	
최대 회전 속도(무부하)	6 800 rpm	

플런지쏘	TSV 60 KEBQ	TSV 60 KEB
경사도	0° ~ 4	15°
0°에서 절단 깊이	0 - 62	mm
45°에서 절단 깊이	0 - 45 mm	
톱날 측정	168 x 1.8 x	20 mm
기기 치수 측정(집진 연결부 포함) (LxWxH)	414 x 180 x 259 mm	
무게(전원 연결선 포함)	6 k	<u> </u>

스코어링	
소비 전력	190 W
110 V - 버전	150 W
최대 회전 속도(무부하)	22 000 rpm
가이드 레일 FS를 사용할 때 권 장되는 절단 깊이	최대 2.0 mm
절단 폭	1.95 - 2.5 mm

5 공구 구성 요소

5.1 주 장치

- [1-1] 조절 플레이트
- [1-2] 속도 제어 장치
- [1-3] 킥백스톱 기능 OFF 버튼
- [1-4] 킥백스톱 기능의 상태 LED
- [1-5] 손잡이
- [1-6] 툴 교체용 레버
- [1-7] 스위치 ON 로크
- [1-8] 전원 스위치
- [1-9] 집진 연결부
- [1-10] 각도 조절용 회전 버튼
- [1-11] 케이블 가이드
- [1-12] 전원 연결 케이블
- [1-13] 톱날의 시작 위치/종료 위치(양측)
- [1-14] 스코어링 설정용 레버
- [1-15] 절단 깊이 스톱용 2단 분할 눈금(가이드 레일 포함/미포함)
- [1-16] 재연마 톱날용 절단 깊이 조절 나사
- [1-17] 절단 깊이 스톱
- [**1-18**] 각도자
- [1-19] 절단선 표시기
- [1-20] 모니터링창 및 칩날림 방지 장치

[1-21] 스캔 웨지

[1-22] 보호 커버

5.2 스코어링

- [1-23] 스코어링 스핀들 스톱 버튼
- [1-24] 스코어링 절단 폭/절단 깊이 조절 휠
- [1-25] 스코어링 측면 편심 조절 휠
- [1-26] 스코어링 레버 활성화/비활성화

사용 설명서의 전반부에 이와 관련된 그림이 나와 있습니다.

그림 또는 설명에 나온 액세서리의 일부는 공급 범위에 포함되지 않습니다.

6 최초 작동

허용되지 않은 전압 또는 주파수! 사고 위험

- 전원 전압 및 전원 주파수는 형식판에 제시된 내용과 일치해야 합니다.
- ► 북미 지역에서는 120 V / 60 Hz의 Festool 공 구만 사용할 수 있습니다.

전원 케이블을 연결하고 분리하기 전에는 반 드시 공구의 스위치를 끄십시오!

해당 기기로 스플린터 가드를 절단한 가이드 레일만 사용합니다(12.2 단원 참조).

(i) 제품 공급 시 스코어링은 주 톱날에 대해 정렬되어 있지 않습니다. 스코어링을 처음 사용하기 전에 조절하십시오(8 단원 참조, 8.4/8.5 순서).

6.1 plug it 케이블 연결 방식의 기기

TSV 60 KEBQ 에 적용.



주의

베이어닛 피팅이 완전하게 잠기지 않은 경우 plug it 연결부 과열.

화재 위험

 전동 공구의 전원을 켜기 전에 베이어닛 피팅이 전원 케이블에 완전하게 닫힌 후 고정되어 있는 지 확인하십시오.

전원 연결 케이블의 연결 및 분리 [1-12] 그림을 [2] 참조하십시오.

7 주 장치 조절



경고

상해 위험, 감전

► 공구 장비에서 작업하기 전에 항상 전원 플러그 를 전원 소켓으로부터 분리하십시오!

7.1 전자 장치

속도 제어 장치

속도는 조정 휠 [1-2]을 사용해서 속도 범위(기술 제 원 참조) 내에서 무단계식으로 설정할 수 있습니다. 이를 통해 각 표면에 따라 절단 속도를 최적으로 조 절할 수 있습니다.

소재별 회전 속도 단계	
원목(경질, 연질)	6
칩보드 및 고밀도 섬유 합판	3 - 6
적층 목재, 블록 보드, 베니어판 및 코팅판	6
합판, 광물성 소재	4 - 6
석고 및 시멘트 계열 칩보드 및 섬유판	1 - 3
15 mm 이하 알루미늄 플레이트 및 프로파 일	4 - 6
플라스틱, 섬유 강화 플라스틱(GRP), 종이 및 섬유	3 - 5
아크릴 유리	4 - 5

과부하 보호

기기 과부하 시 전자식 과부하 보호 장치가 모터의 손상을 방지합니다. 이런 경우 모터는 정지한 뒤 부 하 해제 후에 다시 작동합니다. 재가동 시 기기를 다 시 켜야 합니다.

브레이크

톱 은 전자 제동이 가능합니다. 전원을 끄면 전자 제 동에 의해 약 2초 내에 톱날이 정지됩니다.

경고! 스코어링에는 전자 브레이크가 없으며 톱 장치를 차단한 후 약 2초 후에 따라서 작동합니다.

온도 유지

모터 온도가 너무 높으면 전원 공급 및 속도가 감소합니다. 전동 공구는 모터 팬을 통해 빠르게 냉각될수 있도록 감소된 출력으로만 작동합니다. 냉각이되고 나면 전동 공구가 자동으로 다시 높은 출력으로 작동합니다.

7.2 절단 깊이 설정

절단 깊이 0 - 62 mm는 절단 깊이 스톱 [**3-1**]으로 조절됩니다.

톱 장치는 설정된 절단 깊이까지만 내릴 수 있습니다.



가이드 레일이 사용되지 않은 경우 절단 깊이

최대 62 mm



가이드 레일 FS가 사용된 경우 절단 높이

최대 57 mm

7.3 절단 각도 조절하기

0° ~ 45°

- ▶ 회전 버튼 [4-1]을 푸십시오.
- ► 톱 장치를 원하는 절단 각도 [4-2]까지 돌리십 시오.
- ▶ 회전 버튼 [4-1]을 잠그십시오.
- (j) 두 위치(0°및 45°)는 출고 시 설정된 것이며, 서비스 센터에서 재조정할 수 있습니다.



앵글 컷에서는 모니터링창 [1-20]을 가장 위쪽의 위치로 미십시오!

7.4 톱날 선택

Festool 톱날은 컬러 링 표시로 구분됩니다. 링의 색상은 톱날 사용에 적합한 소재를 나타냅니다. 필요한 톱날 정보에 유의하십시오(3.2 장 참조).

색상	소재	기호
황색	목재	
적색	합판, 광물성 소재	HPL HPL/TRESPA®
녹색	석고 및 시멘트 계열 칩보드 및 섬유판	
청색	알루미늄, 플라스틱	AL ACRYL

7.5 톱날 교체 [5]

상해 위험, 감전

► 공구 장비에서 작업하기 전에 항상 전원 플러그 를 전원 소켓으로부터 분리하십시오!

주의

뜨겁고 날카로운 공구 비트로 인한 부상 위험.

- ▶ 낡거나 손상된 공구 비트는 사용하지 않습니다.
- ▶ 공구 비트 취급 시 보호장갑을 착용하십시오.

톱날 제거

- ► 톱날을 변경하기 전에 톱을 0° 위치로 돌리고, 최대 절단 깊이를 조절하십시오.
- ▶ 레버 [5-3]를 스톱 위치까지 내리십시오. 레버 는 톱이 정지된 상태에서만 조작하십시오!
- 톱 장치가 고정될 때까지 아래로 내리십시오.
- ► 톱 장치를 단단한 바닥 위에 내려 놓으십시오. 톱날 측면을 위로 올리십시오.
- ▶ 나사 [5-5]를 알렌 키 [5-2]로 푸십시오.
- ► 톱날 [5-8]을 제거하십시오.

스캔 유닛 청소

경고! 스캔 유닛이 오염되면 킥백스톱 기능에 영향을 주고, 이로 인해서 톱날 제동에 방해가 될 수 있습니다.

- ► 톱 장치를 손잡이로 단단히 잡고, 레버 [5-3]를 닫은 후, 톱 장치를 밑으로 끝까지 내리십시오.
- ▶ 레버 [5-3]를 다시 풀고, 톱 장치를 고정시키십시오.
- ► 바람을 불거나 브러시를 사용해 스캔 유 닛 [5-9]을 청소하십시오.

톱날 삽입

경고! 나사와 플랜지의 오염 상태를 점검하고, 손상되지 않은 깨끗한 부품만 사용하십시오!

- ► 톱 장치를 손잡이로 단단히 잡고, 레버 [5-3]를 스톱 위치까지 내리십시오.
- ▶ 톱 장치가 고정될 때까지 아래로 내리십시오.
- ▶ 새 톱날을 끼우십시오.

경고! 톱날 [5-7]과 톱 [5-4]의 회전 방향이 일 치해야 합니다! 이를 지키지 않을 경우 심각한 상해를 입을 수 있습니다.

- ► 당김 핀이 안쪽 플랜지의 리세스 안에 들어가도 록 바깥쪽 플랜지 [5-6]를 삽입하십시오.
- ▶ 나사 [5-5]를 단단히 조이십시오.
- ► 톱 장치를 손잡이로 단단히 잡고 레버 [5-3]를 닫은 뒤 톱 장치를 다시 위로 올리십시오.

7.6 집진

분진으로 인한 건강 위협

- 집진 작업 없이는 절대 작업을 진행하지 마십시 오.
- ▶ 국가별 규정에 유의하십시오.
- 발암성 물질을 절단할 경우에는 항상 국가 규정 에 따라 적합한 집진기를 사용하십시오. 집진백 을 사용하지 마십시오.

자체 집진 기능

- ► 집진백 [6-3] 커넥터 [6-2] 를 우측으로 돌려 흡입 노즐 [6-1] 에 고정하십시오.
- ► 먼지를 비울 때는 집진백 커넥터를 좌측으로 돌려 흡입 노즐에서 분리하십시오.

보호 커버 안이 막히면 안전 기능에 영향을 줄 수 있습니다. 따라서 막힘 방지를 위해 집진기를 최대 집 진 성능으로 작업하는 것이 더 좋습니다.

MDF 등을 절단할 때 정전기가 발생할 수 있습니다. 정전 방지 집진 호스와 이동식 집진기를 함께 사용 해 작업하십시오.

Festool 이동식 집진기

Festool 이동식 집진기의 집진 연결부 [6-1]에는 직경 27/32 mm 또는 36 mm(끼임 현상을 줄이기 위해 36 mm 사용 권장)의 집진 호스를 연결할 수 있습니다.

직경 27 집진 호스의 연결 장치는 앵글 커넥 터 [6-4] 안으로 연결합니다. 직경 36 집진 호스의 연결 장치는 앵글 커넥터 [6-4] 위로 연결합니다.

주의! 정전 방지 집진 호스를 사용하지 않으면 정전 기가 발생할 수 있습니다. 작업자 감전 또는 전자 부 품 손상이 발생할 수 있습니다.

8 스코어링 조절

⚠ 🔏 경고

상해 위험, 감전

► 공구 장비에서 작업하기 전에 항상 전원 플러그 를 전원 소켓으로부터 분리하십시오!

8.1 스코어링(scoring) 조절

스코어링은 주 톱날을 향하여 정렬되어야 합니다. 작업 결과는 여러 주변 조건에 의해 영향을 받습니 다. 따라서 실제 절단 작업 전에 테스트 절단을 실시 해 스코어링의 정렬을 점검합니다.

- 톱 장치와 가이드 레일 사이의 가이드 유격을 올 바르게 설정합니다(단원 12.2참조). 이는 올바 른 절단 작업을 위해 중요합니다.
- ► 주 톱날의 원하는 절단 깊이를 설정합니다(단원 7.2참조). (권장 사항: 가공물 바닥면의 가장자리가 매끄럽게 가공될 수 있도록 톱니 돌출이 최소 12 mm 수준에 달하는 것이 좋습니다.)

- ► 한정적인 스코어링 깊이에서 스코어링을 활성화 하고 테스트 절단을 실시합니다.
- ▶ 측면 편심을 조절하여(단원 8.4참조) 스코어링 너트와 주 톱날을 정렬합니다. 추가적인 테스트 절단을 통한 점검.
- ► 스코어링의 절단 폭을 주 톱날에 대해 조절합니다(단원 8.5참조). 여기에서도 테스트 절단이 반드시 필요합니다.
- ▶ 원하는 절단 결과가 나올 때까지 이전의 두 단계 를 반복합니다.
- i 테스트 절단 시에는 항상 가공물 내로 최소 20 30 cm 정도 삽입되게 하십시오. 립 컷을 시작하는 영역에서는 가공물의 나머지 부분보다 스코어링 깊이가 더 커지고 이를 통해 스코어링 너트의 폭이 더 커질 수 있습니다.

8.2 스코어링 활성화/비활성화 [7]

활성화(ON)

- ▶ [7-1] 스코어링 레버를 위쪽 스토퍼까지 돌려서 활성화/비활성화하십시오.
- ☑ 주 장치가 인입되면 스코어링 톱날도 인입됩니다.

비활성화(OFF)

- ► 스코어링 레버를 [**7-1**] 90° 아래로 돌려서 활성 화/비활성화합니다.
- ☑ 주 장치가 스코어링 톱날 없이 인입됩니다.
- (i) 원래 깊이 및 절단 설정은 그대로 유지됩니다.
- 8.3 완전한 스코어링 조절 기능 활성화/비활성 화 [8]

활성화

- 스코어링 조절용 레버 [8-1]를 우측 스토퍼까지 젖히십시오.
- ☑ 주 톱날의 인입이 차단됩니다.
- (i) 주 톱날은 스코어링 시 함께 회전합니다.

비활성화

- ► 완전한 스코어링 조절을 위한 레버 [8-1]를 왼쪽 스토퍼까지 젖히십시오.
- ☑ 주 톱날이 설정된 절단 깊이로 절단합니다.

8.4 측면 편심 조절 [9]



소코어링 톱날의 절단은 주 톱날 절단의 중앙에서 정렬됩니다.

- ► 조절 휠의 측면 편심 [9-1]을 조절합니다. 시계 방향()으로 회전: 스코어링 유닛이 가이드 레일에서 이동합니다.
- (i) 한 바퀴 회전:
 - 0.5 mm 축 방향 경로
- (i) 랫치:
 - 0.025 mm 축 방향 경로

8.5 스코어링 절단 폭(절단 깊이) 조절 [10]



스코어링 톱날은 원뿔형 톱니입니다. 절 단 폭은 절단 깊이로 조절합니다.

- ► 조절 휠에서 [10-1] 절단 폭을 설정합니다. 시계 방향(+)으로 회전: 절단 폭 및 절단 깊이가 증가합니다.
- (j) 한 바퀴 회전:
 - 절단 폭 변경: 0.32 mm
 - 절단 깊이 변경: 1.3 mm
- (i) 랫치:
 - 절단 폭 변경: 0.025 mm
 - 절단 깊이 변경: 0.1 mm
- i 권장사항: 절단 폭은 주 톱날보다 최소한의 폭 만큼만 넓게 조절합니다.

8.6 스코어링 톱날 교체 [11]

경고

상해 위험, 감전

► 공구 장비에서 작업하기 전에 항상 전원 플러그를 전원 소켓으로부터 분리하십시오!

주의

뜨겁고 날카로운 공구 비트로 인한 부상 위험.

- ▶ 낡거나 손상된 공구 비트는 사용하지 않습니다.
- ▶ 공구 비트 취급 시 보호장갑을 착용하십시오.

스코어링 톱날 제거

- 스코어링 활성화(8.2 단원 참조).
- ► 공구 교체용 레버 [11-1]를 스토퍼까지 옮깁니다.
- 톱 장치를 단단한 바닥 위에 내려 놓으십시오. 톱날 측면을 위로 올리십시오.
- ▶ 스핀들 스톱 [11-2]을 누른 상태로 두십시오.
 소형 육각 소켓 렌치 [11-3]가 있는 스크류
 [11-5]를 여십시오(왼 나사).
- ▶ 스코어링 톱날 [11-7]을 제거합니다.

스코어링 톱날 삽입

경고! 스크류 **[11-5]**의 오염 여부를 점검하십시오. 깨끗하고 손상되지 않은 부품만 사용합니다!

- 새 톱날을 삽입하십시오. 위로 압착되는 측면. 경고! 톱날 [11-6]과 톱 [11-4]의 회전 방향이 일치해야 합니다! 이를 지키지 않을 경우 심각한 상해를 입을 수 있습니다.
- ▶ 스핀들 스톱 [11-2]을 누른 상태로 두십시오.
 스크류 [11-5]를 삽입한 뒤 작은 육각 소켓 렌치
 [11-3]로 조이십시오(왼 나사.

8.7 스코어링 부분 집진

- ► 스코어링으로 작업 시 모니터링창 [1-20]을 완 전히 아래로 미십시오.
- ☑ 스코어링 부분에 발생하는 먼지는 집진 장치로 이동합니다.

9 전동 공구를 이용한 작업



작업 시 다음에 제시된 모든 기본 안전 지침 과 규정에 유의하십시오.

시작하기 전

- 사용 전에는 항상 구동 유닛이 톱날과 함께 처음 위치인 하우징 안으로 문제없이 다시 올라가는지 점검하십시오. 위쪽 최종 위치가 확인되지 않으면 톱을 사용하지 마십시오. 회전식 구동유닛은 절대 특정한 절단 깊이로 고정하거나 클램핑하지 마십시오. 톱날 보호 기능이 작동되지 않을 수도 있습니다.
- 사용 전 반드시 플런징 장치의 기능을 점검하고, 기능이 정상적으로 작동할 때만 전동 공구를 사용하십시오.
- 톱날이 단단하게 장착되어 있는지 확인하십시
 오.
- 톱을 사용하기 전에 항상 킥백스톱 기능 (10.5 장 참조)을 점검하십시오.
- 작업 전에 회전 버튼 [1-10]이 단단히 조여졌는
 지 확인하십시오.
- 작업 시 집진 호스 및 전원 연결 케이블이 가공 물이나 가공물 지지대 또는 바닥의 위험 부위에 서 꼬이지 않도록 주의하십시오.
- 전원 연결선이 날카로운 가공물 모서리에 손상되지 않도록 전원 연결선을 케이블 가이드
 [1-11] 안에 넣습니다.
- 가공물을 전압이 흐르지 않는 상태로 반듯하게 놓으십시오.

작업 시

- 가이드 레일 사용 시 스코어링을 반드시 비활성 화합니다! 가이드 레일을 사용하지 않을 경우 톱날이 갑자기 앞쪽으로 이동할 위험이 있습니다. 스코어링 깊이가 클 경우 가공물이 손상되고 모터가 과부하됩니다.
- 작업 시 톱 테이블은 항상 완전한 상태로 설치 하십시오.
- 작업을 할 때는 반드시 양손으로 전동 공구의 손잡이 [1-5]를 잡으십시오. 정확한 작업과 플 런지 기능을 위해 반드시 필요합니다. 플런지 컷을 진행할 때는 가공물 안으로 천천히 그리고 균일하게 통과하십시오.
- 전동 공구는 전원을 켠 상태에서만 가공물 쪽으로 이동시킵니다.
- 톱은 반드시 앞쪽 [16-2]으로 밀고, 절대로 자신을 향해 뒤쪽 으로 당기지 마십시오.

- 이송 속도를 조절해 톱날 절단선의 과열을 방지하고, 플라스틱 절단 시 플라스틱이 녹는 것을 방지하십시오. 절단할 가공물이 단단할수록 이송 속도가 낮아야 합니다.
- 보호 커버가 톱날을 완전히 에워싸지 않은 상태 에서 워크벤치나 바닥 위에 톱을 내려놓지 마십 시오.

9.1 음향 경고 신호

다음 작동 모드 시 음향 경고 신호가 울립니다.

신호음	원인	조치
삐 소리가 한 번 울 림. ∕	기기 과부하	기기 부하 부족.
삐 소리가 계속됨. △△△△	스코어 링 결 함	스코어링을 비활성화 합니다. Festool 서비 스 센터 또는 특약점에 연락하십시오.

9.2 전원 켜기/끄기

스위치 ON 로크를 작동하면 플런지 장치가 해제됩니다.

- ► 스위치 ON 로크 [1-7]를 위로 올리고 ON/OFF 스위치 [1-9]를 누르십시오(누르기 = ON / 풀 기 = OFF).
- ☑ 톱 장치는 아래 방향으로 움직일 수 있습니다. 이때 톱날이 보호 커버 밖으로 나오게 됩니다.

9.3 기준선 따라 절단하기

기준선 **[12-2]**은 0°및 45°절단 시(가이드 레일 미포함) 절단선을 나타냅니다.

9.4 섹션 절단

톱 테이블 앞쪽을 가공물에 올리고, 공구의 스위치를 켜고, 설정된 절단 깊이까지 내린 뒤, 절단 방향으로 미십시오.

9.5 컷아웃 절단(플런지 컷)



킥백 방지를 위해 반드시 다음 지침에 유의해 야 합니다.

- 공구는 항상 톱 테이블 뒤쪽 가장자리를 고정된
 스톱 장치에 갖다 대십시오.
- 가이드 레일을 사용해서 작업할 때는 공구를 가이드 레일 위에 고정시킨 킥백스톱 FS-RSP(액세서리) [16-4]에 가져오십시오.

조치 방법

- ► 공구를 가공물 위에 올리고 스톱 장치(킥백스톱) 에 가져오십시오.
- ▶ 공구 장비를 켭니다.
- ► 공구를 설정된 깊이까지 서서히 내린 뒤 절단 방향으로 미십시오.
- ☑ 표시선 [12-1]은 절단 깊이가 최대일 때 그리고 가이드 레일을 사용할 때 톱날(직경 168 mm) 의 맨앞쪽과 맨뒤쪽의 절단 지점을 나타냅니다.

스코어링을 이용한 플런지 컷

일부 경우에서는 우선적으로 스코어링으로만 작업한 뒤(8.3 단원 참조) 주 톱날을 이용한 분리 절단을 두 번째 단계로 실시해야 할 수 있습니다. 주 톱날을 이용한 분리 절단 시 스코어링을 비활성화합니다(8.2 단원 참조).

9.6 스코어링으로 절단하기

스코어링은 주 톱날보다 약간 더 넓게 가공물의 표면을 사전 절단합니다. 이에 따라 주 톱날이 표면과 직접적으로 접촉하지 않으며 거스러미가 방지됩니다.

\triangle

경고

부상 위험

스코어 절단 시 가공물의 절단 모서리기 극도로 날 카로워집니다. 이 경우 손가락, 전원선 등이 절단 될 위험이 있습니다.

- ▶ 절단 가장자리를 만지지 마십시오.
- ▶ 전원선은 항상 절단 모서리에서 멀리 두십시오.



주의

스코어링 톱날 회전 시 상해 위험 주 장치에 문제가 생기는 경우(과부하) 주 장치는 정지하지만 스코어링 톱날이 계속해서 작동할 수 있습니다.

- 톱날에 전원이 연결되어 있는 한 톱날 영역을 절대로 만지지 마십시오.
- ▶ 가이드 레일을 부착한 뒤 올바른 유격을 설정합니다.
- ▶ 원래 절단을 실시하기 전에 적합한 테스트 절단 으로 스코어링 정렬을 점검합니다(8.1 단원 참 조).
- ► 2 4 m/min의 권장 이송 속도로 절단(1 m 절 단 시 약 15 - 30초에 해당됩니다).
- j 최고의 정확도를 구현하기 위해서는 가이드 레일을 연결시킨 상태로 작업하지 마십시오.

10 킥백스톱

10.1 킥백스톱 기능



경고

부상 위험

킥백스톱 기능이 킥백 방지를 전적으로 보장할 수 는 없습니다.

항상 작업에 집중하고, 안전 지침과 주의사항에 유의하십시오.

작업 중에 킥백이 발생하면 톱이 불필요하게 들어올 려질 수 있습니다. 스캔 웨지 [13-1]는 작업 시 톱이 가공물이나 레일에서 불필요하게 들어올려지는 것(킥백)을 탐색하고, 톱날 퀵브레이크를 작동합니다(그림 13A 참조). 이렇게 해서 킥백 위험이 줄어들게 됩니다. 그렇지만 킥백을 완전히 배제할 수는 없습니다.

킥백스톱 기능의 상태 LED

색상	의미
녹색	킥백스톱 기능이 활성화되어 있습니다.
주황 색	킥백스톱 기능이 비활성화되어 있습니다.
주황 색 깜 박임	킥백스톱 기능이 활성화되어 있지 않습니다. 스캔 웨지가 가공물이나 가이드 레일 위에 닿기 전에 톱이 작동되었습니다. 톱 테이블이 불완전한 상태로 놓여 있습니다. 톱이 완전한 상태로 LED가 녹색으로 변경됩니다. 그렇지 않을 경우 킥백스톱 기능 (10.5 장 참조)을 점검하십시오
적색 깜박 임	킥백스톱 기능이 작동되었습니다.

10.2 킥백스톱 기능의 불필요한 작동

편평하지 않은 가공물 위에서 가이드 레일 없이 작업하는 경우 킥백스톱 기능이 불필요하게 작동할 수있습니다(그림 **13B** 참조).

스캔 웨지 [13-1]는 가공물을 따라서 탐색합니다. 가공물의 리세스에서는 스캔 웨지의 위치가 가공물 이나 가이드 레일로부터 들어올려진 위치와 같아집 니다. 그렇기 때문에 킥백스톱 기능이 작동됩니다. 이때는 킥백스톱 기능 없이 작업해야 할 수도 있습 니다(10.4 장 참조).

10.3 킥백스톱 기능이 작동된 후의 조치 톱이 불필요하게 들어올려지면서 작동됨(킥백)

- ► 톱이 들어올려진 원인을 조사하고, 해결합니다.
- ▶ 기기의 손상 여부를 점검합니다.
- ▶ 스캔 웨지의 손상 여부를 점검합니다.
- ▶ 킥백스톱 기능을 점검합니다(10.5장 참조).

킥백스톱 기능이 불필요하게 작동된 후

- ► ON/OFF 스위치를 해제하고, 킥백스톱 기능의 상태 LED가 더이상 깜박이지 않을 때까지 기다 리십시오.
- 실제로 킥백스톱 기능이 불필요하게 작동한 것 인지(10.2 장 참조) 또는 킥백인지 확인하십시 오.
- 우선 킥백스톱 기능을 활성화한 상태로 계속 작업하십시오. 가이드 레일 없이 작업할 때 가공물이 편평하지 않아서 킥백스톱 기능이 여러 번 작동할 가능성이 있을 경우만 킥백스톱 기능을 비활성화하십시오(10.4 장 참조).

10.4 킥백스톱 기능 없이 작업



경고

부상 위험

킥백스톱 기능이 비활성화된 상태에서는 톱날이 의도치 않게 들어올려진 경우 제동되지 않습니다.

▶ 가이드 레일 없이 작업할 때 가공물이 편평하지 않아서 킥백스톱 기능이 여러 번 불필요하게 작 동할 가능성이 있을 경우만 킥백스톱 기능을 비 활성화하십시오.

킥백스톱 기능 비활성화

- ▶ 킥백스톱 기능 OFF 버튼을 누릅니다.
- ► 10초 내에 ON/OFF 스위치를 누른 상태로 유지 합니다.
- ☑ 킥백스톱 기능은 ON/OFF 스위치에서 손을 뗄 때까지 계속 비활성화 상태로 유지됩니다.
- i 톱의 전원을 켜기 전에만 킥백스톱 기능을 비활성화할 수 있습니다.

10.5 킥백스톱 기능 점검하기



경고

돌출된 톱날로 인한 상해 위험.

- ▶ 가이드 레일에서 기능 점검을 실시하십시오.
- ▶ 기능 점검 전:
 - 톱날을 탈거합니다.
 - 스코어링을 활성화합니다.
 - 절단 깊이를 0 mm(FS)로 설정합니다.
- ▶ 절단 깊이를 0 mm(FS)로 설정합니다.
- ▶ 장비를 가이드 레일에 놓으십시오.
- ▶ 기기를 켜십시오.
- ► 킥백스톱 기능 OFF 버튼을 5 초 이내에 최소한 0.5 초 간격으로 4 번 누르십시오.
- ☑ 킥백스톱 기능의 상태 LED가 적색과 녹색으로 번갈아 가며 깜박입니다.
- ▶ 15 초 이내
 - ▶ 톱 장치를 아래로 내리십시오.
 - ▷ 기기 뒷면을 들어올렸다가 다시 내리십시 오.
- ☑ 신호음이 울리고, 상태 LED가 녹색으로 켜집니다. 킥백스톱 기능이 문제없이 작동합니다.

신호음이 울리지 않고, 상태 LED가 녹색으로 켜지지 않으면, 킥백스톱 기능이 정상적으로 작동하지 않습니다.

- ► 기능 점검이 올바르게 진행되었는지 확인하십시 오.
- ► 톱날 뒤쪽의 스캔 유닛을 청소하십시오(톱날 교 체 참조).
- ☑ 기능 점검이 여전히 문제라면 더 이상 기기를 사용해서는 안 됩니다. Festool 서비스 센터에 연락하십시오.

11 유지보수 및 관리

경고

상해 위험, 감전

- ► 유지보수 및 관리 작업을 하기 전에 항상 전원 플러그를 전원 소켓으로부터 분리하십시오!
- ▶ 모터 하우징을 열어서 작업해야 하는 모든 유지 보수 작업 및 수리 작업은 공인된 고객 서비스 센터를 통해서만 진행할 수 있습니다.

고객 서비스 및 수리는 제조사 또는 서비스 센터에 서만 진행해야 합니다. Festool의 정품 교체용 부품 만 사용하십시오.

상세 정보: www.festool.co.kr/service

다음 지침을 준수하십시오.

- 손상된 안전 장치 및 부품(예: 공구 교체용 레 버 [1-6])은 공인된 서비스 센터에서 적절한 서 비스를 받거나, 사용 설명서에 별도로 표시되어 있지 않다면 새것으로 교체해야 합니다.
- ► 전체 구동 유닛을 안전한 위쪽 최종 위치로 밀어 넣는 리턴 스프링의 상태와 정상적인 기능을 점 검하십시오.
- 충분히 환기가 이루어지도록 하우징 내 환기구 는 항상 깨끗하게 유지하십시오.
- 전동 공구에서 파편과 칩을 제거할 때는 모든 구 멍에서 집진하십시오. 절대로 보호 커버 [1-22] 를 열지 마십시오.
- ► 석고 및 시멘트 계열 섬유판을 작업할 때는 특히 공구 장비를 깨끗이 청소하십시오. 전동 공구 및 ON/OFF 스위치의 환기구를 유분기 없는 건조 한 압축 공기로 청소해줍니다. 그렇지 않을 경우 전동 공구 하우징 내에서 및 ON/OFF 스위치 부 분에서 석고 함유 분진이 침전되고, 공기 수분과 결합한 후 경화될 수 있습니다. 이로 인해 스위 치 기계장치가 손상될 수 있습니다.

11.1 재연마한 톱날

조절 나사 [14-1]를 이용해 재연마한 톱날의 절단 깊이를 정확하게 조절할 수 있습니다.

- ► 절단 깊이 스톱 [14-2]을 (가이드 레일을 포함 하여) 0으로 설정하십시오.
- 톱 장치를 해제하고, 스톱 위치까지 내리십시오.
- ► 톱날이 가공물에 닿을 때까지 조절 나사 [14-1] 를 밖에서 안으로 조이십시오.
- 스코어링 톱날은 다이아몬드 톱니여서 재연마 할 수 없습니다.

11.2 톱 테이블의 흔들림

- 절단 각도를 설정할 때 톱 테이블을 편평한 바 닥면에 놓아야 합니다.
- ▶ 톱 테이블이 흔들리면 설정을 다시 해야 합니다.

11.3 각도자 정렬

그림을 참조하십시오 15.

액세서리 **12**

Festool이 허용하는 액세서리 및 소모품만 사용하 십시오. www.festool.co.kr

다른 액세서리와 소모품을 사용할 경우 공구의 안전 을 보장할 수 없으며 심각한 사고가 발생할 수 있습 니다.

Festool은 공구를 다양하고 효과적으로 구성할 수 있도록, 표시된 액세서리 외에도 다음과 같이 폭넓 은 시스템 액세서리를 제공합니다.

- 킥백 스토퍼 FS-RSP
- 앵글 스톱 FS-WA 및 FS-WA/90°
- 이동식 톱 테이블 및 작업대 STM 1800
- 다기능 테이블 MFT/3

12.1 톱날, 기타 액세서리

Festool은 다양한 소재를 신속하고 깔끔하게 컷팅 할 수 있도록 Festool 톱의 모든 사용 용도에 적합 한 톱날을 제공하고 있습니다.

12.2 가이드 시스템

가이드 레일을 사용하면 정확하고 깔끔하게 절단할 수 있고, 동시에 가공물 표면의 손상을 방지할 수 있 습니다.

가이드 시스템은 폭넓은 액세서리와 함께 정확한 앵 글 컷, 마이터 컷 및 조정 작업을 수행합니다. 클램프 [16-5] 고정 방식으로 단단한 고정과 안전한 작업 이 가능합니다.

► 조절 플레이트 [16-1]로 톱 테이블이 가이드 레 일 위에서 가이드되는 간격을 조절하십시오.

가이드 레일을 처음 사용하기 전에 다음과 같이 스 프린터 가드 [16-3]를 절단하십시오.

- 공구의 회전속도를 6단으로 맞추십시오.
- 공구의 전체 가이드 플레이트를 가이드 레일 뒤 쪽 끝에 올려 놓으십시오.
- 공구 장비를 켭니다.
- 최대 절단 깊이까지 천천히 공구를 내리고, 스프 린터 가드의 전체 길이를 중단없이 자르십시오.
- ☑ 스프린터 가드의 가장자리가 절단면과 정확하게 일치합니다.
- (i) 스프린터 가드를 자르기 위해 테스트 목재에 가이드 레일을 올려 놓으십시오.

(i) TSV 60 제품은 다른 Festool 플런지쏘보다 훨씬 더 바깥쪽에서 스플린터 가드를 절단합니 다. 가이드 레일에 사용하는 톱 장치로 항상 스 플린터 가드를 절단합니다.

스코어링을 적용하는 스플린터 가드

스코어링으로 절단 작업을 할 때 스플린터 가드는 완전한 절단 표시기의 역할을 합니다. 스플린터 가 드 없이 절단을 해서는 안 되며, 그렇지 않을 경우 가 이드 레일이 깔끔하게 설치되지 않고 우수한 작업 결과를 달성할 수 없습니다.

12.3 크로스 컷팅 가이드 레일

크로스 커팅 가이드 레일은 목재 및 패널재에 대한 톱 작업에 적합합니다.

이를 사용하면 정밀하고 깔끔한 절단이 가능하며. 특히 앵글 컷을 쉽고 반복 정확도를 높여 진행할 수 있습니다. 톱질을 마치면 톱이 자동으로 초기 위치 로 복귀됩니다.

크로스 커팅 가이드 레일 FSK 사용 설명서에 유의 하십시오.

13 환경



공구 장비를 가정용 쓰레기로 폐기하지 마십 시오! 공구, 액세서리 및 포장재는 환경 보호 법에 따라 재활용됩니다. 통용되는 국가별 규정을 준수하십시오.

14 일반 지침

14.1 데이터 보호 관련 정보

해당 전동 공구는 공구 데이터 및 작동 데이터 자동 저장을 위한 칩이 포함되어 있습니다. 저장된 데이 터에 직접적인 개인 정보는 포함되어 있지 않습니 다.

해당 데이터는 특수 장치를 이용하여 비접촉 방식으 로 판독 가능하며, Festool에서 고장 진단, 수리 및 보증 처리와 품질 개선 또는 후속 개발 용도로만 사 용할 수 있습니다. 고객의 명문상 동의 없이는 이러 한 용도 외에 다른 목적으로 데이터를 활용할 수 없 습니다.

15 문의

경기도 의왕시 맑은내길 67, 501-2호(오 전동, 에이엘티지식산업센터)

(우) 16071

전화: 02-6022-6740 팩스: 02-6022-6799

https://www.festool.co.kr

ALT Center A 5F, Malgeunnae-gil 67

Uiwang-si, Gyeonggi-do

16071

phone: 02-6022-6740 fax: 02-6022-6799

https://www.festool.co.kr

Contents

1	Symbols	23
2	Safety warnings	
3	Intended use	
4	Technical data	28
5	Parts of the device	28
6	Commissioning	29
7	Main unit settings	
8	Scoring unit settings	
9	Working with the electric power tool	33
10	KickbackStop	34
11	Service and maintenance	36
12	Accessories	36
13	Environment	37
14	General information	37
15	Contact us	37

1 Symbols



Warning of general danger



Warning of electric shock



Read the operating manual and safety warnings.



Wear ear protection.



Wear protective gloves when changing tools.



Wear a dust mask.



Wear protective goggles.



Pull out the mains plug



Disconnecting the mains power cable



Connecting the mains power cable



Direction of rotation of saw and the saw blade



KickbackStop function



Electro-dynamic run-down brake



Do not dispose of it with domestic waste.



Tool contains a chip which stores data. See section 14.1



Tip or advice



Safety class II

2 Safety warnings

2.1 General power tool safety warnings

WARNING! Read all safety warnings, instructions, illustrations and specifications provided with this power tool. Failure to follow all instructions listed below may result in electric shock, fire and/or serious injury.

Save all warnings and instructions for future reference.

The term "power tool" in the warnings refers to your mains-operated (corded) power tool or battery-operated (cordless) power tool.

1 WORK AREA SAFETY

- Keep work area clean and well lit. Cluttered or dark areas invite accidents.
- b. Do not operate power tools in explosive atmospheres, such as in the presence of flammable liquids, gases or dust. Power tools create sparks which may ignite the dust or fumes.
- Keep children and bystanders away while operating a power tool. Distractions can cause you to lose control.

2 ELECTRICAL SAFETY

- a. Power tool plugs must match the outlet. Never modify the plug in any way. Do not use any adapter plugs with earthed (grounded) power tools. Unmodified plugs and matching outlets will reduce risk of electric shock.
- b. Avoid body contact with earthed or grounded surfaces, such as pipes, radiators, ranges and refrigerators. There is an increased risk of electric shock if your body is earthed or grounded.
- c. **Do not expose power tools to rain or wet conditions.** Water entering a power tool will increase the risk of electric shock.
- d. Do not abuse the cord. Never use the cord for carrying, pulling or unplugging the power tool. Keep cord away from heat, oil, sharp edges or moving parts. Damaged or entangled cords increase the risk of electric shock.
- e. When operating a power tool outdoors, use an extension cord suitable for outdoor

- **use.** Use of a cord suitable for outdoor use reduces the risk of electric shock.
- f. If operating a power tool in a damp location is unavoidable, use a residual current device (RCD) protected supply. Use of an RCD reduces the risk of electric shock.

3 PERSONAL SAFETY

- a. Stay alert, watch what you are doing and use common sense when operating a power tool. Do not use a power tool while you are tired or under the influence of drugs, alcohol or medication. A moment of inattention while operating power tools may result in serious personal injury.
- b. Use personal protective equipment. Always wear eye protection. Protective equipment such as a dust mask, non-skid safety shoes, hard hat or hearing protection used for appropriate conditions will reduce personal injuries.
- c. Prevent unintentional starting. Ensure the switch is in the off-position before connecting to power source and/or battery pack, picking up or carrying the tool. Carrying power tools with your finger on the switch or energising power tools that have the switch on invites accidents.
- d. Remove any adjusting key or wrench before turning the power tool on. A wrench or a key left attached to a rotating part of the power tool may result in personal injury.
- e. **Do not overreach. Keep proper footing and balance at all times.** This enables better control of the power tool in unexpected situations.
- f. Dress properly. Do not wear loose clothing or jewellery. Keep your hair and clothing away from moving parts. Loose clothes, jewellery or long hair can be caught in moving parts.
- g. If devices are provided for the connection of dust extraction and collection facilities, ensure these are connected and properly used. Use of dust collection can reduce dust-related hazards.
- h. Do not let familiarity gained from frequent use of tools allow you to become complacent and ignore tool safety principles. A careless action can cause severe injury within a fraction of a second.

4 POWER TOOL USE AND CARE

- a. Do not force the power tool. Use the correct power tool for your application. The correct power tool will do the job better and safer at the rate for which it was designed.
- b. **Do not use the power tool if the switch does not turn it on and off.** Any power tool
 that cannot be controlled with the switch is
 dangerous and must be repaired.
- c. Disconnect the plug from the power source and/or remove the battery pack, if detachable, from the power tool before making any adjustments, changing accessories, or storing power tools. Such preventive safety measures reduce the risk of starting the power tool accidentally.
- d. Store idle power tools out of the reach of children and do not allow persons unfamiliar with the power tool or these instructions to operate the power tool. Power tools are dangerous in the hands of untrained users.
- e. Maintain power tools and accessories.
 Check for misalignment or binding of moving parts, breakage of parts and any other condition that may affect the power tool's operation. If damaged, have the power tool repaired before use. Many accidents are caused by poorly maintained power tools.
- f. **Keep cutting tools sharp and clean.** Properly maintained cutting tools with sharp cutting edges are less likely to bind and are easier to control.
- g. Use the power tool, accessories and tool bits etc. in accordance with these instructions, taking into account the working conditions and the work to be performed. Use of the power tool for operations different from those intended could result in a hazardous situation.
- h. **Keep handles and grasping surfaces dry, clean and free from oil and grease.** Slippery handles and grasping surfaces do not allow for safe handling and control of the tool in unexpected situations.

5 SERVICE

- Have your power tool repaired by qualified specialists only and always use original spare parts. This ensures that the safety of the power tool is maintained.
- Only use original parts for repairs and maintenance. The use of incompatible ac-

cessories or spare parts can result in electric shocks or other injuries.

2.2 Safety instructions for specific circular saws

 Only for AS/NZS: The tool shall always be supplied via residual current device with a rated residual current of 30 mA or less.

Cutting procedures

- DANGER: Keep hands away from cutting area and the blade. Keep your second hand on auxiliary handle, or motor housing. If both hands are holding the saw, they cannot be cut by the blade.
- Do not reach underneath the workpiece.
 The guard cannot protect you from the blade below the workpiece.
- Adjust the cutting depth to the thickness of the workpiece. Less than a full tooth of the blade teeth should be visible below the workpiece.
- Never hold the workpiece in your hands or across your leg while cutting. Secure the workpiece to a stable platform. It is important to support the work properly to minimise body exposure, blade binding, or loss of control.
- Hold the power tool by the insulated handle surfaces if you intend to perform work that entails a risk of cutting into hidden power cables or the tool's own power cable. Contact with live cables transfers an electric current to metal components on the electric power tool and causes electric shocks.
- When ripping, always use a rip fence or straight edge guide. This improves the accuracy of cut and reduces the chance of blade binding.
- Always use blades with correct size and shape (diamond versus round) of arbour holes. Blades that do not match the mounting hardware of the saw will run off-centre, causing loss of control.
- Never use damaged or incorrect blade washers or bolt. The blade washers and bolt were specially designed for your saw, for optimum performance and safety of operation.

Kickback causes and related warnings

 kickback is a sudden reaction to a pinched, jammed or misaligned saw blade, causing

- an uncontrolled saw to lift up and out of the workpiece toward the operator;
- when the blade is pinched or jammed tightly by the kerf closing down, the blade stalls and the motor reaction drives the unit rapidly back toward the operator;
- if the blade becomes twisted or misaligned in the cut, the teeth at the back edge of the blade can dig into the top surface of the wood causing the blade to climb out of the kerf and jump back toward the operator.

Kickback is the result of saw misuse and/or incorrect operating procedures or conditions and can be avoided by taking proper precautions as given below.

- Maintain a firm grip with both hands on the saw and position your arms to resist kickback forces. Position your body to either side of the blade, but not in line with the blade. Kickback could cause the saw to jump backwards, but kickback forces can be controlled by the operator, if proper precautions are taken.
- When blade is binding, or when interrupting a cut for any reason, release the trigger and hold the saw motionless in the material until the blade comes to a complete stop. Never attempt to remove the saw from the work or pull the saw backward while the blade is in motion or kickback may occur. Investigate and take corrective actions to eliminate the cause of blade binding.
- When restarting a saw in the workpiece, centre the saw blade in the kerf so that the saw teeth are not engaged into the material. If a saw blade binds, it may walk up or kickback from the workpiece as the saw is restarted.
- Support large panels to minimise the risk of blade pinching and kickback. Large panels tend to sag under their own weight.
 Supports must be placed under the panel on both sides, near the line of cut and near the edge of the panel.
- Do not use dull or damaged blades. Unsharpened or improperly set blades produce narrow kerf causing excessive friction, blade binding and kickback.
- Blade depth and bevel adjusting locking levers must be tight and secure before making the cut. If blade adjustment shifts while cutting, it may cause binding and kickback.

 Use extra caution when sawing into existing walls or other blind areas. The protruding blade may cut objects that can cause kickback.

Guard function

- Check the guard for proper closing before each use. Do not operate the saw if the guard does not move freely and enclose the blade instantly. Never clamp or tie the guard so that the blade exposed. If the saw is accidentally dropped, the guard may be bent. Check to make sure that the guard Moves freely and does not touch the blade or any other part, in all angles and depths of cut.
- Check the operation and condition of the guard return spring. If the guard and the spring are not operating properly, they must be serviced before use. The guard may operate sluggishly due to damaged parts, gummy deposits, or a build-up of debris.
- Assure that the base plate of the saw will not shift while performing the "plunge cut". Blade shifting sideways will cause binding and likely kick back.
- Always observe that the guard is covering the blade before placing the saw down on bench or floor. An unprotected, coasting blade will cause the saw to walk backwards, cutting whatever is in its path. Be aware of the time it takes for the blade to stop after switch is released.

Function of the feeler wedge [1-21] (Kickback-Stop function)

- Every time the saw blade is replaced, clean the feeler unit [5-9] by blowing it out or using a brush. Any contamination of the feeler unit may impair the Kickback-Stop function and therefore prevent the saw blade from being stopped.
- Do not operate the saw if the feeler wedge is bent. Even the slightest damage can slow the braking of the saw blade.

2.3 Safety instructions for the preassembled saw blade

Usage

- The maximum speed specified on the saw blade must not be exceeded and the speed range must be adhered to.
- The pre-installed saw blade is only designed for use in circular saws.

- The scoring unit saw blade is only intended for use in the Festool TSV 60. It is intended for processing wood and wood-like materials, as well as for machining plastics in the form of a coating or plastic solid material.
- Proceed with extreme care when unpacking, packing and handling the tool (e.g. installing it in the machine). There is a risk of injury from extremely sharp cutting edges!
- When handling the tool, wearing safety gloves provides a more secure hold of the tool and further reduces the risk of injury.
- Circular saw blades with cracked bodies must be replaced. Repair is not permitted.
- Circular saw blades with a combination design (soldered saw teeth) with saw tooth thickness smaller than 1 mm must no longer be used.
- WARNING! Do not use tools with visible cracks or blunt or damaged cutting edges.

Installation and mounting

- Tools must be clamped in such a way that they cannot come loose during operation.
- When assembling the tools, it must be ensured that the clamping takes place on the tool hub or the clamping surface of the tool, and that the cutting edges do not come into contact with other components.
- Do not lengthen the key or tighten by hitting with a hammer.
- The clamping surfaces must be cleaned to remove contamination, grease, oil and water
- Clamping screws must be tightened according to the manufacturer's instructions.
- Only securely installed rings, e.g. rings that have been pressed in or those that are held in position by an adhesive bond, may be used to adjust the hole diameter of circular saw blades to the spindle diameter of the machine. The use of loose rings is not permitted.
- After changing the saw blade, the machine needs to be checked and, where necessary, readjusted according to the operating instructions.

Service and maintenance

- Repairs or resanding work must only be carried out by Festool customer service workshops or experts.
- The tool design must not be changed.

- Deresinify and clean the tool regularly (cleaning agent with pH between 4.5 and 8).
- Blunt edges can be resharpened on the clamping surface to a minimum cutting edge thickness of 1 mm.
- The scoring unit saw blade cannot be resharpened.
- Only transport the tool in suitable packaging risk of injury!

2.4 Further safety instructions

- Wear suitable personal protective equipment: Ear protection, safety goggles, a dust mask for work that generates dust.
- Harmful/toxic dust may be produced during your work (e.g. paint containing lead, certain types of wood or metals). Contact with or inhalation of this dust may pose a risk for the operating personnel or persons in the vicinity. Comply with the safety regulations that apply in your country.
- Use suitable breathing protection to protect your health. In enclosed spaces, ensure that there is sufficient ventilation and connect a mobile dust extractor.
- This power tool cannot be installed in a work bench. The power tool may become unsafe and cause serious accidents if installed in benches from other manufacturers or self-manufactured work benches.
- Check whether there are any signs of damage to the housing components, such as cracks or stress whitening. Have any damaged components repaired before using the power tool.
- Use appropriate detection devices to look for any hidden supply lines or consult your local utility company. If the insertion tool makes contact with live cables, it can result in fire and electric shock. Damage to a gas pipe can lead to an explosion. Penetration of a water pipe can result in damage to property.
- Do not lift or carry the power tool by the cable.

2.5 Aluminium processing

When processing aluminium, the following measures must be taken for safety reasons:



Wear protective goggles.

Regularly clean dust deposits from the motor housing on the power tool.

- Use a saw blade suitable for cutting aluminium.
- Close the viewing window.
- Install an upstream residual-current circuit breaker (RCD, PRCD).
- When sawing panels, they must be lubricated with petroleum, but thin-walled profiles (up to 3 mm) can be sawed without lubrication.

2.6 Emission levels

The levels determined in accordance with EN 60745 are typically:

Sound pressure level $L_{PA} = 93 \text{ dB(A)}$

Sound power level $L_{WA} = 101 \text{ dB(A)}$

Uncertainty K = 3 dB



CAUTION

Noise emissions created while working with the power tool may damage your hearing.

► Always use ear protection.

Vibration emission level a_h (vector sum for three directions) and uncertainty K measured in accordance with EN 60745:

Sawing wood $a_h < 2.5 \text{ m/s}^2$

 $K = 1.5 \text{ m/s}^2$

Sawing metal $a_h < 2.5 \text{ m/s}^2$

 $K = 1.5 \text{ m/s}^2$

The specified emission levels (vibration, noise)

- are used to compare machines.
- They are also used for making preliminary estimates regarding vibration and noise load during operation.
- They represent the primary applications of the power tool.



CAUTION

The emission values may deviate from the specified values. This is dependent on how the tool is used and the type of workpiece being machined.

- Assess the actual load during the entire operating cycle.
- ▶ Depending on the actual load, suitable protective measures must be defined in order to protect the operator.

3 Intended use

Circular saws are designed for sawing wood, materials similar to wood, gypsum and cement-bonded fibre materials and plastics. When fitted with the special saw blades for aluminium that are offered by Festool, these machines can also be used for sawing aluminium.

Materials containing asbestos must NOT be processed.

Do not use cutting or abrasive wheels.



The user is liable for improper or non-intended use.

3.1 Scoring unit

The scoring unit is only permitted to be activated in combination with the guide rail and when processing:

- Wooden materials and wood-based materials
- Plastics in the form of a coating or plastic solid material

3.2 Saw blades

Only use saw blades with the following dimensions:

- Saw blades according to EN 847-1
- Saw blade diameter 168 mm
- Cutting width 1.8 mm
- Locating bore 20 mm
- Standard blade thickness 1.2 mm
- Suitable for speeds of up to 9 500 min⁻¹

For splinter-free cuts, the following saw blades are suitable for use in combination with the scoring unit:

- Circular saw blade HW 168 x 1.8 x 20 WD42
- Circular saw blade HW 168 x 1.8 x 20 TF52

For the scoring unit, only use Festool saw blades with the following data:

- Saw blades according to EN 847-1
- Saw blade diameter 47 mm
- Cutting width 1.9-2.5 mm
- Locating bore 6.35 mm
- Standard blade thickness 1.6 mm
- Suitable for speeds of up to 26 000 rpm

Festool saw blades comply with EN 847-1. Only saw materials for which the saw blade in question has been designed.

4 Technical data

Circular saw	TSV 60 KEBQ	TSV 60 KEB
Removable mains power cable (plug-it)	✓	×
Power consumption	1 500 W	
Speed	3 000 - 6 800 rpm	
Max. speed (no-load)	6 800 rpm	
Inclination	0° to 45°	
Cutting depth at 0°	0-62 mm	
Cutting depth at 45°	0-45 mm	
Saw blade dimensions	168 x 1.8 x 20 mm	
Device dimensions (incl. extractor connector) (L x W x H)	414 x 180 x 259 mm	
Weight (without mains power cable)	6 kg	

Scoring unit	
Power consumption	190 W
110 V version	150 W
Max. speed (no-load)	22 000 rpm
Recommended cutting depth with FS guide rail	max. 2.0 mm
Cutting width	1.95-2.5 mm

5 Parts of the device

9	I di la di liic device
5.1	Main unit
[1-1]	Adjustable jaws
[1-2]	Speed control
[1-3]	KickbackStop function OFF button
[1-4]	KickbackStop function status LED
[1-5]	Handles

- [1-6] Lever for changing the tool
- [1-7] Safety lock
- [1-8] On/off switch
- [1-9] Extractor connector
- [1-10] Rotary knobs for adjusting the angle
- [1-11] Cable routing
- [1-12] Mains power cable
- [1-13] Start/end position of saw blades (both sides)
- [1-14] Lever for adjusting the scoring unit only
- [1-15] Split scale for the cutting depth stop (with/without a guide rail)
- [1-16] Cutting depth adjusting screw for reconditioned saw blades
- [1-17] Cutting depth stop
- [1-18] Angle scale
- [1-19] Gauge marker
- [1-20] Viewing window/chip guard
- [1-21] Feeler wedge
- [1-22] Protective lid

5.2 Scoring unit

- [1-23] Button for the scoring unit spindle stop
- [1-24] Adjusting wheel for cutting width/cutting depth of scoring unit
- [1-25] Adjusting wheel for lateral offset of the scoring unit
- [1-26] Lever for activating/deactivating the scoring unit

The specified illustrations appear at the beginning of the Operating Instructions.

Accessories shown or described are not always included in the scope of delivery.

6 Commissioning

WARNING

Unauthorised voltage or frequency. Risk of accidents

- ► The mains voltage and the frequency of the power source must correspond to the specifications on the name plate.
- ► In North America, only Festool machines with the voltage specifications 120 V / 60 Hz may be used.

Always switch off the machine before connecting and disconnecting the mains power cable.

Only use guide rails with a splinter guard that has been cut into using this machine (see section 12.2).

The scoring unit is not aligned with the main saw blade when delivered. Adjust the scoring unit before using it for the first time (see section 8, in the order 8.4/8.5).

6.1 Machines with plug-it connection

Applies to TSV 60 KEBQ.



CAUTION

Heating of the plug it connection if the bayonet fitting is not completely locked.

Risk of burns

▶ Before switching on the power tool, make sure that the bayonet fitting at the mains cable is closed fully and locked.

Connecting and detaching the mains power cable [1-12] see Fig. [2].

7 Main unit settings



WARNING

Risk of injury, electric shock

Always disconnect the mains plug from the socket before performing any work on the machine.

7.1 Electronics

Speed control

You can continuously adjust the speed within the speed range using the adjusting wheel [1-2] (see "Technical data"). This enables you to optimise the cutting speed to suit each surface.

Speed range per material	
Solid wood (hard, soft)	6
Chipboard and hardboard	3-6
Laminated wood, blockboard, veneered and laminated panels	6
Laminate, mineral materials	4-6
Plaster- and cement-bonded chipboard and fibreboard	1–3
Aluminium panels and profiles up to 15 mm	4–6
Plastics, fibre-reinforced plastics, paper and fabric	3–5
Acrylic glass	4-5

Overload protection

Electronic overload protection protects the motor from damage if there is an extreme overload. In this case, the motor remains at a standstill and only starts up again once the load has been removed. To restart the machine, you must switch it on again.

Brake

The saw comes with an electronic brake. The saw blade is stopped electronically within approximately two seconds of switching off the machine.

WARNING! The scoring unit does not have an electronic brake and continues to run for approx. 2 seconds after the saw has been switched off.

Temperature cut-out

The power supply is restricted and the speed reduced if the motor exceeds a certain temperature. The power tool continues operating at reduced power to allow the ventilator to cool the motor quickly. The power tool starts up again automatically once the motor has cooled sufficiently.

7.2 Adjusting the cutting depth

The cutting depth can be set at 0-62 mm at the cutting depth stop [3-1].

The saw unit can now be pushed downwards as far as the cutting depth that is set.



Cutting depth without guide rail max. 62 mm



Cutting depth with FS guide rail max. 57 mm

7.3 Adjusting the cutting angle

Between 0° and 45°

- ➤ Open the rotary knobs [4-1].
- Swivel the saw unit to the desired cutting angle [4-2].
- ► Close the rotary knobs [4-1].
- i Both positions (0° and 45°) are set at the factory and can be readjusted by the customer service team.



When making angled cuts, slide the viewing window [1-20] to the highest position.

7.4 Selecting the saw blade

Festool saw blades are identified by a coloured ring. The colour of the ring represents the material for which the saw blade is suited.

Refer to the necessary saw blade data (see section 3.2).

Colour	Material	Symbol
Yellow	Wood	
Red	Laminate, mineral ma- terial	HPL HPL/TRESPA
Green	Plaster- and cement- bonded chipboard and fibreboard	
Blue	Aluminium, plastic	AL ACRYL

7.5 Changing the saw blade [5]



WARNING

Risk of injury, electric shock

 Always disconnect the mains plug from the socket before performing any work on the machine.



CAUTION

Risk of injury from hot and sharp tool.

- ► Do not use any blunt or faulty tools.
- Wear protective gloves when handling a tool.

Removing the saw blade

- Swivel the saw to 0° before replacing the saw blade and adjust the maximum cutting depth.
- ► Turn the lever [5-3] as far as it will go. Operate the lever only when the saw is at a standstill!
- Push the saw unit down until it engages.
- Lay the saw on its side on a stable base.
 Saw blade side upwards.
- ► Loosen the screw [5-5] using the Allen key [5-2].
- Remove the saw blade [5-8].

Cleaning the feeler unit

WARNING! Any contamination of the feeler unit may impair the KickbackStop function and therefore prevent the saw blade from being stopped.

- ► Hold the saw unit securely by its handle, close the lever [5-3] and press the saw unit all the way down.
- ► Release the lever **[5-3]** again and click the saw unit into place.
- Clean the feeler unit [5-9] by blowing it out or using a brush.

Inserting the saw blade

WARNING! Check the screws and flange for contamination and only use clean and undamaged parts.

- ► Hold the saw unit securely by its handle and turn the lever **[5-3]** as far as it will go.
- ► Push the saw unit down until it engages.
- ► Insert a new saw blade.
 - **WARNING!** The direction of rotation of the saw blade **[5-7]** and saw **[5-4]** must match. Serious injuries may occur in the event of non-compliance.
- ► Insert the outer flange [5-6] in such a way that the pulling peg engages in the recess of the inner flange.
- ► Tighten the screw [5-5].
- ► Hold the saw unit securely by its handle, close the lever [5-3] and guide the saw unit back upwards.

7.6 Dust extraction

<u>(1)</u>

WARNING

Health hazard posed by dust

- Always work with an extractor.
- Comply with national regulations.
- When sawing carcinogenic materials, always connect a suitable extraction mobile in accordance with national regulations. Do not use the chip collection bag.

Independent extraction

- Secure the connection piece [6-2] of the dust collection bag [6-3] at the extractor connector [6-1] with a clockwise rotation.
- To empty, remove the connection piece of the dust collection bag from the extractor connector with an anti-clockwise rotation.

Blockages in the guard may impair safety features. To avoid blockages, it is therefore better to work with a mobile dust extractor at full suction power.

Static charge may occur when sawing (e.g. MDF). If this is the case, work with a mobile dust extractor and an antistatic suction hose.

Festool mobile dust extractor

A Festool mobile dust extractor with a suction hose diameter of 27/32 mm or 36 mm (36 mm recommended due to the reduced risk of clogging) can be connected to the extractor connector **[6-1]**.

The adapter on a 27 diameter suction hose is inserted into the angle adapter [6-4]. The adapter on a 36 diameter suction hose is inserted over the angle adapter [6-4].

CAUTION! A static charge may build up if no antistatic suction hose is used. The user may receive an electric shock and the power tool's electronics may be damaged.

8 Scoring unit settings



WARNING

Risk of injury, electric shock

Always disconnect the mains plug from the socket before performing any work on the machine.

8.1 Scoring unit adjustment procedure

The scoring unit must be aligned with the main saw blade. The work result is influenced by a wide range of limiting conditions. Therefore, check the alignment of the scoring unit before actually cutting with test cuts.

- ➤ Set the guide play between the saw and guide rails correctly (see section 12.2). This is important for a precise cut.
- ➤ Set the required cutting depth for the main saw blade (see section 7.2). (Recommendation: The tooth projection should be at least 12 mm if good edge quality is to be achieved on the underside of the workpiece.)
- Perform a test cut with the scoring unit activated at a low scoring depth.
- Adjust the lateral offset (see section 8.4) until the scoring groove is aligned with the cut of the main saw blade. Check by performing further test cuts.
- ➤ Adjust the cutting width of the scoring groove on the main saw blade (see section 8.5). Test cuts are also imperative here.
- Repeat both of the previous steps until the required cut result is achieved.
- Always drive at least 20 30 cm into the workpiece with the test cuts. At the start of a rip cut, there may be a larger scoring depth and therefore a wider scoring groove than in the rest of the workpiece.

8.2 Activating/deactivating the scoring unit [7]

Activating (ON)

- ► Turn the lever for activating/deactivating [7-1] upwards as far as it will go.
- ✓ Plunging the main unit also plunges the scoring unit saw blade.

Deactivating (OFF)

- ► Turn the lever for activating/deactivating [7-1] 90° downwards.
- ☑ The main unit plunges without the scoring unit saw blade.
- The original depth and cutting width settings remain.

8.3 Activating/deactivating the scoring unit adjustment only [8]

Activating

- ► Turn the lever for adjusting the scoring unit only [8-1] to the right as far as it will go.
- ☑ The main saw blade is prevented from cutting.
- i The main saw blade also rotates when scoring.

Deactivating

- ► Turn the lever for adjusting the scoring unit only [8-1] to the left as far as it will go.
- ☑ The main saw blade saws at the cutting depth set.

8.4 Setting the lateral offset [9]

The cut by the scoring unit blade must be centrally aligned with the cut by the main saw blade.

Set the lateral offset on the adjusting wheel [9-1].

Turning in a clockwise direction (**R**): The scoring unit moves away from the guide rail.

(i) One revolution:

0.5 mm axial travel

(i) One catch:

0.025 mm axial travel

8.5 Adjusting the cutting width (cutting depth) of the scoring unit [10]



The scoring unit saw blade has a conical cutting tooth, which means that the cutting width is controlled through the cutting depth.

Adjust the cutting width [10-1] on the adjusting wheel.

Turning in a clockwise direction (+): The cutting depth and cutting width increase.

(i) One revolution:

- Change to the cutting width: 0.32 mm
- Change to the cutting depth: 1.3 mm

(i) One catch:

- Change to the cutting width: 0.025 mm
- Change to the cutting depth: 0.1 mm
- Recommendation: Only set the cutting width to be slightly wider than the cutting width of the main saw blade.

8.6 Changing the scoring unit saw blade [11]

WARNING

Risk of injury, electric shock

 Always disconnect the mains plug from the socket before performing any work on the machine.



CAUTION

Risk of injury from hot and sharp tool.

- ► Do not use any blunt or faulty tools.
- Wear protective gloves when handling a tool.

Removing the scoring unit saw blade

- Activate the scoring unit (see section 8.2).
- ► Turn the lever for changing the tool [11-1] as far as it will go.
- Lay the saw on its side on a stable base.
 Saw blade side upwards.
- Press and hold the spindle stop [11-2].
 Loosen the screw [11-5] using the small Allen key [11-3] (left-hand thread).
- ► Remove the scoring unit saw blade [11-7].

Inserting the scoring unit saw blade

WARNING! Check the screw [11-5] for contamination. Only use clean and undamaged parts.

- Insert the new saw blade. Imprinted side upwards.
 - **WARNING!** The direction of rotation of the saw blade [11-6] and saw [11-4] must match. Serious injuries may occur in the event of non-compliance.
- Press and hold the spindle stop [11-2]. Insert the screw [11-5] and tighten using the small Allen key [11-3] (left-hand thread).

8.7 Dust extraction on the scoring unit

- When working with the scoring unit, slide the viewing window [1-20] fully down.
- ☑ Dust generated at the scoring unit is directed to the dust extraction.

9 Working with the electric power tool

When working on the machine, observe all of the safety warnings that are listed at the start as well as the following rules:

Before starting

Before each use, check whether the drive unit with the saw blade correctly and fully swivels back up into its initial position in the protective housing. Do not use the saw if the upper end position is not secured. Never clamp or secure the swivelling drive unit at a specific cutting depth. This would mean that the saw blade is not protected.

- Check the function of the plunging mechanism prior to use and do not use the power tool if it does not function correctly.
- Check that the saw blade is securely in place.
- Before each use of the saw, check that the KickbackStop is functioning properly (see Section 10.5).
- Make sure that the rotary knob [1-10] is tightened before starting work.
- Make sure that extractor hose and mains power cable do not snag the entire saw cut, either on the workpiece, the workpiece support or hazards on the ground.
- To prevent the mains power cable from being damaged by sharp workpiece edges, hang the mains power cable in the cable holder [1-11].
- Position the workpiece so that it is stressfree and level.

During work

- It is imperative to deactivate the scoring unit when using without the guide rail.
 When using without the guide rail, there is a danger of the saw moving forwards unexpectedly. The larger cutting depth on the scoring unit causes damage to the workpiece and the motor may become overloaded.
- Position the saw's plate such that it is always completely level during any work.
- When working, always hold the power tool with both hands on the handles [1-5]. This is a prerequisite for precise work and is essential for plunge-cutting. Plunge into the workpiece slowly and evenly.
- Only guide the power tool towards the workpiece when it is switched on.
- Always push the saw forwards [16-2], and never towards yourself.
- Adapt the infeed speed to prevent the cutters on the saw blade from overheating and prevent plastic materials from melting during cutting. The harder the material to be sawn, the lower the feed speed needs to be.
- Make sure that the guard completely surrounds the saw blade before placing the saw on the worktop or on the ground.

9.1 Acoustic warning signals

Acoustic warning signals sound if the following operating states arise:

Signal	Cause	Action
Beeps once.	Machine overloa- ded	Reduce the load on the machine.
Beeps continuously.	Scoring unit faulty	Deactivate the scoring unit. Contact a Festool service workshop or specialist dealer.

9.2 Switch on/off

Pressing the switch-on lock unlocks the plunging mechanism.

- Slide the switch-on lock [1-7] upwards and press the on/off switch [1-9] (press = ON / release = OFF).
- ☑ The saw unit can then be moved downwards. This causes the saw blade to emerge from the protective cover.

9.3 Sawing along the scribe mark

The gauge marker [12-2] displays the cutting line for 0° and 45° cuts (without a guide rail).

9.4 Cutting sections

Position the machine with the front part of the saw table on the workpiece, switch on the machine, push it down to the set cutting depth and push it forward in the cutting direction.

9.5 Sawing cut-outs (plunge cuts)

In order to avoid kickbacks, the following instructions must always be followed when plunge cutting:

- Always position the machine with the rear edge of the saw table against a fixed stop.
- When working with the guide rail, position the machine at the FS-RSP kickback stop (accessory) [16-4], which is clamped to the guide rail.

Procedure

- Place the machine on the workpiece and position it at a stop (KickbackStop).
- Switch on the machine.
- Slowly push the machine down to the set cutting depth and push it forward in the cutting direction.
- ☑ The marks [12-1] indicate the absolute front and rear cutting points of the saw blade (Ø 168 mm) when using the saw at maximum cutting depth with the guide rail.

Plunge cuts with scoring unit

In some cases, it may be necessary to work initially with the scoring unit only (see section 8.3) and carry out the through cutting with the main

saw blade in a second procedure. Deactivate the scoring unit when through cutting with the main saw blade (see section 8.2).

9.6 Saws with a scoring unit

The scoring unit cuts the surface of the workpiece slightly wider than the main saw blade. This means that the main saw blade no longer comes into contact with the surface, preventing splinters.

\triangle

WARNING

Risk of injury

Sawing with the scoring unit creates extremely sharp cutting edges on the workpiece. These pose a cutting hazard for fingers, mains power cables, etc.

- ► Do not touch the cutting edge.
- ► Always keep mains power cables away from the cutting edge.



CAUTION

Risk of injury from the rotating scoring unit saw blade

In the event of a fault in the main unit (e.g. overload), the main saw blade may stop while the scoring unit saw blade continues.

- ► Never reach into the area of the saw blades while the saw is connected to the mains.
- Fit the guide rail and set the correct play.
- Check the alignment of the scoring unit before actually cutting with appropriate test cuts (see section 8.1).
- Saw at the recommended feed speed of 2– 4 m/min. (For a 1 m cut, this equates to a time of approx. 15–30 seconds).
- For maximum precision, do not work with connected guide rails.

10 KickbackStop

10.1 KickbackStop function



WARNING

Risk of injury

The KickbackStop does not guarantee complete protection against a kickback.

 Always concentrate on your work and refer to the safety instructions and warnings.

A kickback while working may cause the saw to lift unintentionally.

The feeler wedge [13-1] detects unintentional lifting (kickback) of the saw from the workpiece or a rail during work and triggers the quick-acting braking of the saw blade (Fig. 13A).

This reduces the risk of a kickback. However, it cannot be entirely ruled out.

KickbackStop function status LED

Colour	Meaning
Green	The KickbackStop function is active.
Orange	The KickbackStop function is deactivated.
Flashing orange	The KickbackStop function is not active. The saw was started up before the feeler wedge was pressed against the workpiece or a guide rail. The saw's plate is not positioned such that it is completely level. Once the saw has been positioned such that is completely level, the LED will switch to green. If this is not the case, check the Kickback-Stop function (see Section 10.5)
Flashing red	The KickbackStop function has been triggered.

10.2 Unintentional triggering of the KickbackStop function

Working without a guide rail on an uneven workpiece may cause the KickbackStop function to trigger unintentionally (Fig. **13B**).

The feeler wedge **[13-1]** runs along the work-piece. If there is a recess in the workpiece, the position of the feeler wedge will correspond to the position when the workpiece or guide rail is lifted. This triggers the KickbackStop function. It may then be necessary to work without the KickbackStop function (see Section 10.4).

10.3 Procedure after the KickbackStop function has been triggered

Triggered by unintentional lifting (kickback)

- Determine and eliminate any reasons for lifting.
- Check the machine for any damage.
- ► Check the feeler wedge for any damage.
- Check the KickbackStop function (see Section 10.5).

After the KickbackStop function has unintentionally been triggered

- Release the on/off switch and wait until the KickbackStop function status LED is no longer flashing.
- ► Check whether there was an unintentional triggering of the KickbackStop function (see Section 10.2) or a kickback.
- Try first to continue working with an active KickbackStop function. Only deactivate the KickbackStop function if you are working without a rail and your workpiece is so uneven that the KickbackStop function would unintentionally be triggered several times (see Section 10.4).

10.4 Working without the KickbackStop function

\triangle

WARNING

Risk of injury

If the KickbackStop function is deactivated, the saw blade is not stopped when it unintentionally lifts.

 Only deactivate the KickbackStop function if you are working without a rail and your workpiece is so uneven that the Kickback-Stop function would unintentionally be triggered several times.

Deactivate the KickbackStop function

- Press the KickbackStop function OFF button
- Press and hold the on/off switch within ten seconds.
- ☑ The KickbackStop function remains deactivated until the on/off switch is next released.
- The KickbackStop function can only be deactivated before the saw is switched on.

10.5 Checking the KickbackStop function



WARNING

Risk of injury from a protruding saw blade.

- ► Carry out function testing on the guide rail.
- ► Before the function testing:
 - Remove the saw blade.
 - Deactivate the scoring unit,
 - Set the cutting depth to 0 mm (FS).
- ► Set the cutting depth to 0 mm (FS).
- ► Place the machine on the guide rail.
- Switch on the machine.

- Press the KickbackStop function OFF button four times at intervals of at least 0.5 seconds within five seconds.
- The KickbackStop function status LED flashes alternately red and green.
- ► Within 15 seconds
 - ▶ Press the saw unit down.
 - ► Lift the machine at the rear and lower it again.
- A signal sounds, the status LED lights up green. The KickbackStop function operates fault-free.

If no signal sounds and the status LED does not switch to green, the KickbackStop function is not operating fault-free.

- ► Check whether the function testing was carried out correctly.
- ► Clean the feeler unit behind the saw blade (see "Changing the saw blade").
- ☑ If the function testing remains unsuccessful, the machine must no longer be used. Contact your Festool service workshop.

11 Service and maintenance

1.4

WARNING

Risk of injury, electric shock

- Always pull the mains plug from the socket before performing any servicing and maintenance work.
- All maintenance and repair work which requires the motor housing to be opened should always be carried out by an authorised service workshop.

Customer service and repairs must only be carried out by the manufacturer or service workshops. You must only use **original Festool spare parts**.

Further information: www.festool.co.kr/service

Observe the following instructions:

- Damaged safety devices and parts, such as a faulty lever for changing tools [1-6], must be properly repaired or replaced in a recognised specialist workshop, unless otherwise indicated in the operating manual.
- Check the condition and fault-free functioning of the recuperating springs, which push the entire drive mechanism bearing into the upper protected end positions.
- ➤ To ensure constant air circulation, always keep the cooling air openings in the housing clean and free of blockages.

- Use an extractor on all openings in order to remove wood chips and splinters from the power tool. Never open the protective lid [1-22].
- When working with plaster- and cementbonded fibreboards, clean the tool particularly thoroughly. Clean the vents of the power tool and on/off switch using dry, oilfree compressed air. Otherwise, gypsum dust deposits may build up inside the power tool's housing and on the on/off switch and harden when exposed to humidity. This may impair the switching mechanism.

11.1 Reconditioned saw blades

You can use the adjusting screw [14-1] to precisely set the cutting depth for reconditioned saw blades.

- ➤ Set the cutting depth stop [14-2] to 0 mm (with quide rail).
- Unlock the saw unit and push it downwards as far as the stop.
- Screw the adjusting screw [14-1] in until the saw blade comes into contact with the workpiece.
- i The scoring unit saw blade cannot be resharpened because it contains a diamond tooth.

11.2 Saw table wobbles

- The saw table must be on an even surface when adjusting the cutting angle.
- ► If the saw table wobbles, the setting must be implemented again.

11.3 Aligning the angle scale

See figure **15**.

12 Accessories

Always use accessories and consumables approved by Festool. See www.festool.co.kr

The power tool may become unsafe and lead to serious accidents if other accessories and consumables are used.

In addition to the accessories described, Festool also provides a comprehensive range of system accessories that allow you to use your machine more effectively and in diverse applications, e.g.:

- Set-back stop FS-RSP
- Angle stop FS-WA and FS-WA/90°
- Mobile saw table and work bench STM 1800
- Multifunction table MFT 3

12.1 Saw blades, other accessories

In order to saw different materials quickly and cleanly, Festool offers saw blades for all applications and these are specially designed for your Festool saw.

12.2 Guide system

The guide rail enables you to make clean, accurate cuts while simultaneously protecting the surface of the workpiece from damage.

In conjunction with the extensive range of accessories, exact angled cuts, mitre cuts and fitting work can be completed with the guide system. The option of attaching the guide rail securely using clamps [16-5] ensures safer working conditions.

 Adjust the guide play between the saw table and the guide rail using the two adjustable jaws [16-1].

Bed in the splinter guard [16-3] before using the guide rail for the first time:

- Set the machine speed to 6.
- ► Place the machine at the rear end of the quide rail together with the complete quide plate.
- Switch on the machine.
- Push down the machine slowly to the max. preset cutting depth and cut along the full length of the splinter guard without stopping.
- ☑ The edge of the splinter guard now corresponds exactly to the cutting edge.
- (i) Position the guide rail for sawing the splinter guard on a test piece of wood.
- (i) The TSV 60 cuts into the splinter guard further out than a different Festool circular saw. Therefore, always cut into the splinter guard using the saw with which the guide rail is to be used.

Splinter guard with scoring unit

When sawing with a scoring unit, the splinter guard functions only as a gauge marker. Sawing without a splinter quard is not permitted, as this will mean that the guide rail does not sit properly, leading to poor work results.

12.3 Cross cutting guide rail

The cross cutting guide rail is designed for sawing wood and panel materials.

It enables precise and clean cuts, in particular angled cuts can be performed simply and with repeat accuracy. The saw automatically moves back to the initial position after the sawing process.

Observe the instructions in the operating manual for the FSK cross cutting guide rail

13 **Environment**



Do not dispose of the device in the household waste! Recycle devices, accessories and packaging. Observe applicable national regulations.

14 General information

14.1 Information on data privacy

The power tool contains a chip which automatically stores machine and operating data. The data saved cannot be traced back directly to an individual.

The data can be read in a contactless manner using special devices and shall only be used by Festool for fault diagnosis, repair and warranty processing and for quality improvement or enhancement of the power tool. The data shall not be used in any other way without the express consent of the customer.

Contact us 15

경기도 의왕시 맑은내길 67, 501-2호 (오전동, 에이엘티지식산업센터)

(우) 16071

전화: 02-6022-6740 팩스: 02-6022-6799

https://www.festool.co.kr

ALT Center A 5F, Malgeunnae-gil 67

Uiwang-si, Gyeonggi-do

16071

phone: 02-6022-6740 fax: 02-6022-6799

https://www.festool.co.kr